Bonito Capital Corp.

(a subsidiary of Elgin Mining Inc.)

07 August 2013

Ms. Phyllis Beaulieu Manager of Licensing **Nunavut Water Board** P.O. Box 119 Gjoa Haven, NU **X0B 1J0**

Dear Ms. Beaulieu

RE: **Monthly Report for July 2013** Ulu Gold Project, Nunavut, License Number 2BM-ULU0914

Activity at Ulu during July consisted of the AANDC conducting a site inspection on July 5th. A number of action items were identified by the inspector and Elgin is currently in the process of formulating a plan to deal with them.

Action items:

- 1. All fuel is to be stored in secondary containment, and covered to prevent water accumulation in the containment during periods of inactivity.
- 2. Hazardous waste is to be backhauled.
- 3. Sewage at the airstrip is to be backhauled in 2013, and as much hazardous waste as possible removed from site.
- 4. MMG berm is to be repaired or replaced, or MMG fuel removed from site.
- 5. Spill at the airstrip is to be cleaned up as per Spill Contingency Plan.
- 6. Items 1-5 are to be completed and a report submitted to the Inspector by September 30 2013.
- 7. The Monitoring program is to be implemented immediately, or documentation provided to the Inspector by July 31, 2013 that demonstrates authorization of the Board to discontinue Monitoring.
- 8. Waste storage areas are to be clearly identified.
- 9. Waste is to be clearly identified.
- 10. A timeline to address progressive reclamation of drill sites is to be prepared.
- 11. Items 8-10 are to be addressed in the next field season.

2BM-ULU0914

070213-2BM-ULU0914-MONTHLYREPORTJUNE2013 This file is produced electronically with 2 pages

If you have any questions regarding the above, please do not hesitate to contact me.

Sincerely, **Bonito Capital Corp.**

George Friesen Manager of Technical Services

CC: Jim Currie, COO of Elgin Mining Inc.