



Suite 507-700 W. Pender Street,
 Vancouver, BC V6C 1G8
 CANADA
 Tel: +1.778.379.1433

May 29, 2026

Richard Dwyer
 Manager of Licencing
 Nunavut Water Board
 PO Box 119
 Gjoa Haven, NU
 X0B 1J0

Dear Mr. Dwyer,

Re. 2BM-ULU2030 Part J Item 14 – Monthly Monitoring Program, April 2026

Further to Part J Item 14 of 2BM-ULU2030, Blue Star Gold Corp. (Blue Star) is pleased to provide the following in fulfillment of monthly monitoring requirements during periods of site activity. Activities commenced at Ulu Camp on April 4th which included camp operations and waste management. No sampling results are available for April 2026 for monitoring stations in Table 1 as none of the sites had flow to sample.

Table1. Applicable monitoring stations, **April 2026** (active site)

Station ID	Station Description	Comment
ULU-1	Water Intake at West Lake	See Table 2
ULU-2	<i>Sewage effluent discharge point</i>	<i>Inactive, facility decommissioned</i>
ULU-3	<i>Sewage effluent discharge point</i>	<i>Inactive, facility decommissioned</i>
ULU-4	<i>Mine water pumped from underground Mine Sump</i>	<i>No underground operations. Not discharging</i>
ULU-4b	Portal Surface Retention Pond	Frozen.
ULU-5	<i>Settling/Neutralization Pond</i>	<i>Pond not constructed</i>
ULU-6	<i>Settling/Neutralization Pond</i>	<i>Pond not constructed</i>
ULU-7	Runoff from Waste Rock Pile	Not flowing.
ULU-8	Runoff from Ore Pad	Not flowing.
ULU-9	Outflow from East Lake	Not flowing.
ULU-10	<i>Ulu Lake Inflow from East Lake</i>	<i>Inactive, facility decommissioned</i>
ULU-11	Ulu Lake Outflow	Not flowing.
ULU-12	<i>Domestic water intake for new camp</i>	<i>New camp not constructed</i>
ULU-13	<i>Soil treatment facility water holding pond</i>	<i>Pond not constructed</i>
ULU-14	Airstrip Bulk Fuel Storage Facility	Not yet constructed for the season
ULU-15	Landfill Facility	Not flowing.
MW-1, -2, -3	<i>Monitoring well at soil treatment facility</i>	<i>Facility not constructed; wells not installed</i>

Table 2. ULU-1 Daily volume, **APRIL 2026** (domestic and drilling water use).

Date	Volume (m ³)			
	Domestic	Drilling	Core cutting*	Total
1	-	-	-	-
2	-	-	-	-
3	-	-	-	-
4	-	-	-	-
5	-	-	-	-
6	-	-	-	-
7	-	-	-	-
8	-	-	-	-
9	-	-	-	-
10	-	-	-	-
11	2.227	-	-	2.227
12	-	-	-	-
13	-	-	-	-
14	-	-	-	-
15	-	-	-	-
16	-	-	-	-
17	2.201	-	-	2.201
18	-	-	-	-
19	-	-	-	-
20	-	-	-	-
21	-	-	-	-
22	2.207	-	-	2.207
23	-	-	-	-
24	-	-	-	-
25	-	-	-	-
26	-	-	-	-
27	2.276	-	-	2.276
28	-	-	-	-
29	-	-	-	-
30	-	-	-	-
*core cutting water is included in the domestic extraction				

If you have any questions or concerns about this report, please don't hesitate to reach out.

Kindest regards,

Annabelle Perry

Environmental Coordinator

Blue Star Gold Corp.

enviro@bluestargold.ca

778-379-1433

cc. T. Bolt, Kitikmeot Inuit Association
J. Bolt, Crown-Indigenous Relations and Northern Affairs Canada
D. Lindsay, Blue Star Gold Corp