



Suite 507-700 W. Pender Street,
 Vancouver, BC V6C 1G8
 CANADA
 Tel: +1.778.379.1433

June 01, 2026

Richard Dwyer
 Manager of Licencing
 Nunavut Water Board
 PO Box 119
 Gjoa Haven, NU
 X0B 1J0

Dear Mr. Dwyer,

Re. 2BM-ULU2030 Part J Item 14 – Monthly Monitoring Program, MAY 2026

Further to Part J Item 14 of 2BM-ULU2030, Blue Star Gold Corp. (Blue Star) is pleased to provide the following in fulfillment of monthly monitoring requirements during periods of site activity. Activities ongoing at Ulu Camp throughout May included camp operations, compliance monitoring, waste management, and exploration. Results for monitoring stations listed in Table 1 are provided in Table 3.

Table 1. Applicable monitoring stations, **May 2026** (active site).

Station ID	Station Description	Comment
ULU-1	Water Intake at West Lake	See Table 2
ULU-2	<i>Sewage effluent discharge point</i>	<i>Inactive, facility decommissioned</i>
ULU-3	<i>Sewage effluent discharge point</i>	<i>Inactive, facility decommissioned</i>
ULU-4	<i>Mine water pumped from underground Mine Sump</i>	<i>No underground operations. Not discharging</i>
ULU-4b	Portal Surface Retention Pond	<i>No Discharge.</i>
ULU-5	<i>Settling/Neutralization Pond</i>	<i>Pond not constructed</i>
ULU-6	<i>Settling/Neutralization Pond</i>	<i>Pond not constructed</i>
ULU-7	Runoff from Waste Rock Pile	Not flowing.
ULU-8	Runoff from Ore Pad	See Table 3
ULU-9	Outflow from East Lake	See Table 3
ULU-10	<i>Ulu Lake Inflow from East Lake</i>	<i>Inactive, facility decommissioned</i>
ULU-11	Ulu Lake Outflow	See Table 3
ULU-12	<i>Domestic water intake for new camp</i>	<i>New camp not constructed</i>
ULU-13	<i>Soil treatment facility water holding pond</i>	<i>Pond not constructed</i>
ULU-14	Airstrip Bulk Fuel Storage Facility	Not yet constructed for the season
ULU-15	Landfill Facility	See Table 3
MW-1, -2, -3	<i>Monitoring well at soil treatment facility</i>	<i>Facility not constructed; wells not installed</i>

Table 2. ULU-1 Daily volume, **May 2026** (domestic and drilling water use).

Date	Volume (m ³)			
	Domestic	Drilling	Core cutting*	Total
1	0	-	-	0
2	0	-	-	0
3	3.5	-	-	3.5
4	0	-	-	0
5	4	-	-	4
6	0	-	-	0
7	0	-	-	0
8	5	-	-	5
9	0	-	-	0
10	0	-	-	0
11	5	-	-	5
12	0	-	-	0
13	0	-	-	0
14	5.5	-	-	5.5
15	0	-	-	0
16	0	-	-	0
17	0	-	-	0
18	4.5	-	-	4.5
19	0	-	-	0
20	0	-	-	0
21	7	-	-	7
22	0	-	-	0
23	0	-	-	0
24	0	-	-	0
25	0	-	-	0
26	4.13	-	-	4.13
27	0	-	-	0
28	6.05	-	-	6.05
29	0	-	-	0
30	10.76	-	-	10.76
31	0	-	-	0
*core cutting water is included in the domestic extraction				

Table 3. Results for Compliance Stations, **May 2026**. No Results have been received for the sampling completed in May as of the date of this report; they will be included in the next reporting period.

	Units	Detection Limits	ULU-8A	ULU-15	ULU-9	ULU-11
Date						
Flow	L/sec					
pH	Field					
	Lab					
Conductivity	uS/cm	2				
Total Suspended Solids	mg/L	1				
Alkalinity (PP as CaCO3)	mg/L	1				
Alkalinity (Total as CaCO3)	mg/L	1				
Dissolved Chloride (Cl)	mg/L	1				
Dissolved Sulphate (SO4)	mg/L	1.0-5.0				
Fecal Coliforms	CFU/100mL	1				
Total Ammonia (N)	mg/L	0.015-0.075				
Dissolved Nitrite (N)	mg/L	0.01				
Dissolved Nitrate (N)	mg/L	0.01				
Turbidity	NTU	0.1				
Total Mercury (Hg)	ug/L	0.0019				
Total Arsenic (As)	ug/L	0.020-0.10				
Total Cadmium (Cd)	ug/L	0.010-0.0050				
Total Copper (Cu)	ug/L	0.050-0.50				
Total Lead (Pb)	ug/L	0.0050-0.20				
Total Nickel (Ni)	ug/L	0.020-1.0				
Total Zinc (Zn)	ug/L	0.10-5.0				

If you have any questions or concerns about this report, please don't hesitate to reach out.

Kindest regards,

Annabelle Perry

Environmental Coordinator

Blue Star Gold Corp.

enviro@bluestargold.ca

778-379-1433

cc. T. Bolt, Kitikmeot Inuit Association
J. Bolt, Crown-Indigenous Relations and Northern Affairs Canada
D. Lindsay, Blue Star Gold Corp