

Environmental Emergency Contingency Plan

Hamlet of Rankin Inlet

Addendum # 1

Date of Revision

March 31st, 2011

The Following *Addendum* has been prepared in response to the requirements of the Nunavut water Board, as outlined in Part F, Item 3, of NWB License 3AM-GRA1015:

- A. In the event of a spill, the Facilities Manager (CGS, Rankin Inlet; Tel: 1-867-645-8154), or designate, shall act in the role of Spill Response Coordinator.
- B. The quantities of chlorine maintained on site are as follows: 150 lbs. cylinders of chlorine gas at Williams Lake Pump House (quantity = 10); 150 lbs. cylinders of chlorine gas at the Con Shed Storage facility (quantity = 50); 205 L barrels of fluosilicic acid at Williams Lake Pump House (quantity = 2); 205 L barrels of fluosilicic acid at Con Shed Storage Facility (quantity = 40); 20 L pails of calcium hypochlorite (HTH) at Con Shed Storage Facility (quantity = 5).
- C. Spill Response equipment (including sorbents, gloves, shovels garbage bags and overpaks) is located at both the Williams Lake Pump House and Nipissar Lake Pump House, with significant additional supplies located at the Con Shed Storage Facility.
- D. Section 4.0, Part 2, is amended to read “Report the spill immediately to the INAC Water Resources Officer, in Iqaluit, at 1-867-975-4555”.
- E. Appendix B “Nunavut Spill Report”, replaces “NWT Spill Report”
- F. MSDS Sheets are maintained in the office at the Williams Lake Pump House.
- G. The Contact information in Appendix A is amended to include the following:
 - Department of Fisheries and Oceans (Iqaluit): 1-867-979-8000
 - Rankin Inlet Hunters and Trappers Association: 1-867-645-2350