

230120	Nipissar Lake	freshwater	RI	1/29/03	1/30/03	Total Metals (24) by ICP-MS water	Metals, Total	Cadmium	<	0.3	µg/L	0.3
230120	Nipissar Lake	freshwater	RI	1/29/03	1/30/03	Total Metals (24) by ICP-MS water	Metals, Total	Cesium	<	0.4	µg/L	0.4
230120	Nipissar Lake	freshwater	RI	1/29/03	1/30/03	Total Metals (24) by ICP-MS water	Metals, Total	Chromium	<	3	µg/L	3
230120	Nipissar Lake	freshwater	RI	1/29/03	1/30/03	Total Metals (24) by ICP-MS water	Metals, Total	Cobalt	<	1	µg/L	1
230120	Nipissar Lake	freshwater	RI	1/29/03	1/30/03	Total Metals (24) by ICP-MS water	Metals, Total	Copper		6	µg/L	2
230120	Nipissar Lake	freshwater	RI	1/29/03	1/30/03	Iron, Total	Metals, Total	Iron		531	µg/L	30
230120	Nipissar Lake	freshwater	RI	1/29/03	1/30/03	Total Metals (24) by ICP-MS water	Metals, Total	Lead		27	µg/L	1
230120	Nipissar Lake	freshwater	RI	1/29/03	1/30/03	Total Metals (24) by ICP-MS water	Metals, Total	Lithium	<	3	µg/L	3
230120	Nipissar Lake	freshwater	RI	1/29/03	1/30/03	Total Metals (24) by ICP-MS water	Metals, Total	Manganese		41	µg/L	1

Show All | Search | First page | Prev | Next | Last page | Tr

231380	N.P.LAKE P/H 0779- 1	freshwater	RANKIN INLET	6/12/03	6/12/03	Metals (24) by ICP-MS water	Cesium	<	0.1	µg/L	0.1
231380	N.P.LAKE P/H 0779- 1	freshwater	RANKIN INLET	6/12/03	6/12/03	Total Metals (24) by ICP-MS water	Chromium	<	0.3	µg/L	0.3
231380	N.P.LAKE P/H 0779- 1	freshwater	RANKIN INLET	6/12/03	6/12/03	Total Metals (24) by ICP-MS water	Cobalt		0.2	µg/L	0.1
231380	N.P.LAKE P/H 0779- 1	freshwater	RANKIN INLET	6/12/03	6/12/03	Total Metals (24) by ICP-MS water	Copper		7.4	µg/L	0.2
231380	N.P.LAKE P/H 0779- 1	freshwater	RANKIN INLET	6/12/03	6/12/03	Iron, Total	Iron		49	µg/L	30
231380	N.P.LAKE P/H 0779- 1	freshwater	RANKIN INLET	6/12/03	6/12/03	Total Metals (24) by ICP-MS water	Lead		6.9	µg/L	0.1
231380	N.P.LAKE P/H 0779- 1	freshwater	RANKIN INLET	6/12/03	6/12/03	Total Metals (24) by ICP-MS water	Lithium		2.1	µg/L	0.3
231380	N.P.LAKE P/H 0779- 1	freshwater	RANKIN INLET	6/12/03	6/12/03	Total Metals (24) by ICP-MS water	Manganese		8.3	µg/L	0.1
231380	N.P.LAKE P/H 0779- 1	freshwater	RANKIN INLET	6/12/03	6/12/03	Mercury, Total	Mercury	<	0.01	µg/L	0.01
231380	N.P.LAKE P/H 0779- 1	freshwater	RANKIN	6/12/03	6/12/03	Total Metals (24) by	Molybdenum		0.3	µg/L	0.1



TAIGA

Environmental Laboratory

Taiga Home

About Us

Analytical Capabilities

Service Price List

Rush Services

Sampling & Supplies

Consulting Services

Laboratory Assessments

Training

On-line Results

Resources & Links

Prior visitors may wish to visit the following forms directly (Adobe Acrobat Reader required):

Field Sheet

Bottle Order Form

Show All | [Search](#) | [First page](#) | [Prev](#) | [Next](#) | [Last page](#) |

Taiga Sample ID	Client Sample ID	Sample Type	Sampling Location	Sample Collect Date	Sample Received Date	Test Group Name	Lab Section	Parameter Name	Result Flag	Reported Result	Units
231745	Williamson Lake T/P	potable water	Rankin Inlet	7/2/03	7/3/03	Iron, Total	Metals, Total	Iron		45	µg/L
231745	Williamson Lake T/P	potable water	Rankin Inlet	7/2/03	7/3/03	Total Metals (24) by ICP-MS water	Metals, Total	Lead		0.8	µg/L
231745	Williamson Lake T/P	potable water	Rankin Inlet	7/2/03	7/3/03	Total Metals (24) by ICP-MS water	Metals, Total	Lithium		1.8	µg/L
231745	Williamson Lake T/P	potable water	Rankin Inlet	7/2/03	7/3/03	Total Metals (24) by ICP-MS water	Metals, Total	Manganese		3.2	µg/L
231745	Williamson Lake T/P	potable water	Rankin Inlet	7/2/03	7/3/03	Mercury, Total	Metals, Total	Mercury	<	0.01	µg/L
231745	Williamson Lake T/P	potable water	Rankin Inlet	7/2/03	7/3/03	Total Metals (24) by ICP-MS water	Metals, Total	Molybdenum		0.2	µg/L
231745	Williamson Lake T/P	potable water	Rankin Inlet	7/2/03	7/3/03	Total Metals (24) by ICP-MS water	Metals, Total	Nickel		42.3	µg/L
231745	Williamson Lake T/P	potable water	Rankin Inlet	7/2/03	7/3/03	Total Metals (24) by ICP-MS water	Metals, Total	Rubidium		1.6	µg/L

231747	Nipissar Lake	freshwater	Rankin Inlet	7/2/03	7/3/03	Total Metals (24) by ICP-MS water	Metals, Total	Cadmium	< 0.1	µg/L	0.1
231747	Nipissar Lake	freshwater	Rankin Inlet	7/2/03	7/3/03	Total Metals (24) by ICP-MS water	Metals, Total	Cesium	< 0.1	µg/L	0.1
231747	Nipissar Lake	freshwater	Rankin Inlet	7/2/03	7/3/03	Total Metals (24) by ICP-MS water	Metals, Total	Chromium	4.4	µg/L	0.3
231747	Nipissar Lake	freshwater	Rankin Inlet	7/2/03	7/3/03	Total Metals (24) by ICP-MS water	Metals, Total	Cobalt	0.2	µg/L	0.1
231747	Nipissar Lake	freshwater	Rankin Inlet	7/2/03	7/3/03	Total Metals (24) by ICP-MS water	Metals, Total	Copper	11.5	µg/L	0.2
231747	Nipissar Lake	freshwater	Rankin Inlet	7/2/03	7/3/03	Iron, Total	Metals, Total	Iron	1850	µg/L	30
231747	Nipissar Lake	freshwater	Rankin Inlet	7/2/03	7/3/03	Total Metals (24) by ICP-MS water	Metals, Total	Lead	4.8	µg/L	0.1
231747	Nipissar Lake	freshwater	Rankin Inlet	7/2/03	7/3/03	Total Metals (24) by ICP-MS water	Metals, Total	Lithium	1.7	µg/L	0.3
231747	Nipissar Lake	freshwater	Rankin Inlet	7/2/03	7/3/03	Total Metals (24) by ICP-MS water	Metals, Total	Manganese	166	µg/L	0.1
	Nipissar		Rankin				Mercury, Metals,				

233014	Nipissar Lake	freshwater	Rankin Inlet	8/20/03	8/25/03	Ultra Low Dissolved Metals	Metals, Dissolved	Copper	59.0	µg/L	0.08
233014	Nipissar Lake	freshwater	Rankin Inlet	8/20/03	8/25/03	Iron, Dissolved	Metals, Dissolved	Iron		µg/L	30
233014	Nipissar Lake	freshwater	Rankin Inlet	8/20/03	8/25/03	Ultra Low Dissolved Metals	Metals, Dissolved	Lead	30.8	µg/L	0.02
233014	Nipissar Lake	freshwater	Rankin Inlet	8/20/03	8/25/03	Ultra Low Dissolved Metals	Metals, Dissolved	Lithium	1.8	µg/L	0.2
233014	Nipissar Lake	freshwater	Rankin Inlet	8/20/03	8/25/03	Ultra Low Dissolved Metals	Metals, Dissolved	Manganese	30.2	µg/L	0.02
233014	Nipissar Lake	freshwater	Rankin Inlet	8/20/03	8/25/03	Ultra Low Dissolved Metals	Metals, Dissolved	Molybdenum	0.60	µg/L	0.02
233014	Nipissar Lake	freshwater	Rankin Inlet	8/20/03	8/25/03	Ultra Low Dissolved Metals	Metals, Dissolved	Nickel	2.79	µg/L	0.01
233014	Nipissar Lake	freshwater	Rankin Inlet	8/20/03	8/25/03	Ultra Low Dissolved Metals	Metals, Dissolved	Rubidium	1.74	µg/L	0.01
233014	Nipissar Lake	freshwater	Rankin Inlet	8/20/03	8/25/03	Ultra Low Dissolved Metals	Metals, Dissolved	Selenium	< 0.3	µg/L	0.3

[Show All](#) [Search](#) [First page](#) [Prev](#) [Next](#) [Last page](#) [Top](#)

Lk	Inlet	Rankin Inlet	Metals	Dissolved	Metals	Dissolved	Metals	Dissolved	Metals	Dissolved	Metals	Dissolved
233015	Williamson Lk	Rankin Inlet	8/20/03	8/25/03	Iron, Dissolved	Metals, Dissolved	Iron	Metals, Dissolved	Iron	Metals, Dissolved	Iron	Metals, Dissolved
233015	Williamson Lk	Rankin Inlet	8/20/03	8/25/03	Ultra Low Dissolved Metals	Metals, Dissolved	Lead	Metals, Dissolved	Lead	Metals, Dissolved	Lead	Metals, Dissolved
233015	Williamson Lk	Rankin Inlet	8/20/03	8/25/03	Ultra Low Dissolved Metals	Metals, Dissolved	Lithium	Metals, Dissolved	Lithium	Metals, Dissolved	Lithium	Metals, Dissolved
233015	Williamson Lk	Rankin Inlet	8/20/03	8/25/03	Ultra Low Dissolved Metals	Metals, Dissolved	Manganese	Metals, Dissolved	Manganese	Metals, Dissolved	Manganese	Metals, Dissolved
233015	Williamson Lk	Rankin Inlet	8/20/03	8/25/03	Ultra Low Dissolved Metals	Metals, Dissolved	Molybdenum	Metals, Dissolved	Molybdenum	Metals, Dissolved	Molybdenum	Metals, Dissolved
233015	Williamson Lk	Rankin Inlet	8/20/03	8/25/03	Ultra Low Dissolved Metals	Metals, Dissolved	Nickel	Metals, Dissolved	Nickel	Metals, Dissolved	Nickel	Metals, Dissolved
233015	Williamson Lk	Rankin Inlet	8/20/03	8/25/03	Ultra Low Dissolved Metals	Metals, Dissolved	Rubidium	Metals, Dissolved	Rubidium	Metals, Dissolved	Rubidium	Metals, Dissolved
233015	Williamson Lk	Rankin Inlet	8/20/03	8/25/03	Ultra Low Dissolved Metals	Metals, Dissolved	Selenium	Metals, Dissolved	Selenium	Metals, Dissolved	Selenium	Metals, Dissolved
233015	Williamson Lk	Rankin Inlet	8/20/03	8/25/03	Ultra Low Dissolved Metals	Metals, Dissolved	Silver	Metals, Dissolved	Silver	Metals, Dissolved	Silver	Metals, Dissolved

Show All | Search | First page | Prev | Next | Last page | Tr

[illegible]

[Show All](#) | [Search](#) | [First page](#) | [Prev](#) | [Next](#) | [Last page](#) | [Top](#)

234271	Nipplissar Lake	freshwater	Rankin Inlet	10/1/03	10/2/03	Total Metals (24) in water by ICP-MS	Metals, Total	Lead	µg/L
--------	-----------------	------------	--------------	---------	---------	--------------------------------------	---------------	------	------

[Show All](#) [Search](#) [First page](#) [Prev](#) [Next](#) [Last page](#) [Top](#)

No metals results posted for
THIS DATE