





CIRNAC/NWB Comments on City of Iqaluit 2018 Annual Report for Water Licence No. 3AM-IQA1626

Project	City of Iqaluit – 2018 Annual Water Licence Report	Doc Ref	820952 - 0099(1.0)
Project Manager	Josip Deronja	Date	October 16, 2019
Location	Teleconference	Time	3:00 pm EST

Attendance

Name	Initial	Email	Organization
□ Derek Donald	DD	Derek.Donald@nwb-oen.ca	NWB
⊠ Bridget Campbell	ВС	Bridget.Campbell@canada.ca	CIRNAC
⊠ Godwin Okonkwo	GO	Godwin.Okonkwo@canada.ca	CIRNAC
	JD	Josip.Deronja@colliersprojecteaders.com	Colliers Project Leaders
⊠ Erik Marko	EM	Erik.Marko@colliersprojectleaders.com	Colliers Project Leaders
	CM	Cheryl.Manujibeya@colliersprojectleaders.com	Colliers Project Leaders
☐ Jim Clare	JC	Jim.Clare@aecom.com	AECOM

1. General

Item	Description	Owner	Due By
1.1.1	JD requested an extension to the submission deadline for response to outstanding items noted by NWB/ CIRNAC from the City's 2018 Annual Report until October 30, 2019. NWB/ CIRNAC acknowledged that there was no concern to extend the submission deadline.	Info	
1.1.2	The City to communicate the extension request by email to the NWB.	JD/ CM	Oct 17/19

2. Surface Water Management Plan

Item	Description	Owner	Due By
1.2.1	JD confirmed that the City recently completed a Master Drainage Plan that describes the current drainage system for the City. DD confirmed that the submission of the Master Drainage Plan would be adequate in response to the request for a Surface Water Management Plan.	Info	
1.2.2	The City to submit a copy of the Master Drainage Plan in response to the outstanding comments raised by NWB/ CIRNAC.	JD/ CM	Oct 30/19

3. West 40 Landfill - Missing Pond

Item	Description	Owner	Due By
1.3.1	BC noted that in the West 40 Landfill O&M manual, that a pond identified next to the Wood Waste Processing site was not noticed in the field, during a site inspection that was completed by CIRNAC in 2018. JD confirmed that a pond titled 'South Stormwater Holding Pond' was identified in a recent update to the Landfill O&M and Environmental Monitoring and QA/QC Plan, which was approved by NWB.	Info	

Page 1 of 2 colliersprojectleaders.com





Item	Description	Owner	Due By
1.3.2	The City will confirm whether the Wood Waste Processing site still exists and will confirm the existence of a South Stormwater Holding Pond with the City's Consultant facilitating with operations oversight.	JD/ CM	Oct 30/19

4. Deposit of Waste at the End of Federal Road

Item	Description	Owner	Due By
1.4.1	JD and CM clarified that the waste at Federal Road is a legacy from the former occupants – Transport Canada and the Canadian/ US Military.	Info	
1.4.2	The City to confirm ownership of the site, and response accordingly to the NWB/ CIRNAC.	JD/ CM	Oct 30/19

5. Missing Spill Report

Item	Description	Owner	Due By
1.5.1	The City has verified through the Government of Nunavut's Spill Report database and could not identify a record of a spill that was flagged by NWB/CIRNAC in the 2018 Annual Report. There has been no indication that a spill occurred in Iqaluit on February 12, 2018.	Info	
	The City to respond to the outstanding comment and will provide confirmation that no spill exists within the GN's Spill Report database.	JD/ CM	Oct 30/19

6. 2015 Dam Safety Inspection Recommendations

Item	Description	Owner	Due By
1.6.1	The City is currently investigating the extent of repairs that were executed, as per recommendations from a 2015 Dam Safety Inspection.	Info	
1.6.2	DD indicate that he would provide a copy of the 2015 Dam Safety Inspection Report outlining the required recommendations. DD noted that some items that were listed had already been acted upon by the City.	DD	Oct 16/19
1.6.3	The City to response to the outstanding comment and provide confirmation of repairs that were executed as per recommendations in the 2015 DSI report.	JD/ CM	Oct 30/19

7. Circulation

Name	Initial	Email	Organization
	MH	M.Hamp@iqaluit.ca	City of Iqaluit

Distribution: All invited

Circulation

File