

**File: 3AM-IQA1626** 

September 13, 2021

Amy Elgersma Chief Administrative Officer City of Iqaluit Box 460, Iqaluit, NU X0A 0H0 Email: cao@city.iqaluit.nu.ca

RE: Licence No: 3AM-IQA1626, Type "A"; City of Iqaluit; 2020 Annual Report Review

## Dear Amy Elgersma:

The Nunavut Water Board (NWB or Board) has completed the technical review of the 2020 Annual Report (Report) for Type "A" Water Licence 3AM-IQA1626 (Licence) issued to the City of Iqaluit (City or Licensee). The Report was received on March 18, 2021 and submitted as a requirement under Part B of the Licence.

On March 24, 2021, the NWB distributed the Report to the Iqaluit distribution list for review. Comments from Environment and Climate Change Canada (ECCC) and Crown-Indigenous Relations and Northern Affairs (CIRNA) were received on Jun 23, 2021 and June 24, 2021, respectively. In its submission, ECCC stated that it had no comments at the time. The table below provides a brief summary of issues found outstanding during the Report review period. The table provides also deadlines for the Licensee to respond to respective recommendations and concerns. For the intervenors' discussion of these items, please refer to the comment submissions referenced above.

No.	Intervener Recommendation / Concern	Deadline to Respond by and Provide Outstanding Information	
Crown-Indigenous Relations and Northern Affairs (CIRNA)			
1	Include a detailed account of observations and information collected with respect to inspections conducted at the sewage lagoon.	Subsequent annual reports	
2	Document the ultimate disposal method and location for the geotubes.	Subsequent annual reports	
3	Install and use the equipment necessary to record the volume in cubic metres of landfill effluent discharged	Subsequent annual reports	

	during each discharge event.			
4	Include diagrams or maps indicating the locations of	Subsequent annual reports		
4	the various monitoring stations and their locations	Subsequent annual reports		
	relative to the overall layout of the facilities.	C-1		
5	Engage with the Nunavut Water Board, Tower Arctic	Subsequent annual reports		
	Ltd., and the Government of Nunavut as necessary to			
	coordinate water withdrawals within the City of			
	Iqaluit, to ensure total combined abstraction rates only			
	occur when the natural flow in the Niaqunguk River is			
	above 30% of the mean annual discharge and their			
	total combined withdrawals will not exceed 10% of the			
	instantaneous flow of the Niaqunguk River.			
6	Adopt, implement and provide responses to all the	2021 Annual Report		
	recommendations contained within submissions			
	provided in support of the requirements of their Type			
	A water licence.			
Nunavut Water Board (NWB)				
1	Provide the timeline for fulfillment of the	2021 Annual Report		
	recommendations of the Lake Geraldine Dam Safety			
	Inspection 2020 (DSI) dated December 22, 2020.			
2	The NWB notes the following statement in the DSI:	Subsequent annual reports		
	"The deep snow and ice on and around the LG Dam at			
	the time of our inspection may have obstructed visual			
	indicators such as sloughing, slides, bulging or			
	displacement."			
	•			
	The NWB recommends conducting any inspections			
	during summer time.			
3	The DSI states: "In 2020 the City installed a series of	Subsequent annual reports		
	piezometers and thermistors to monitor hydrogeologic	•		
	and thermal environments within the backfill and			
	foundations. There appears to be no formal record of			
	any monitoring or recording of the data from these			
	sensors."			
	The NWB recommends the City conduct proper			
	monitoring of the dam.			
4	The NWB recommends the inclusion of information on	2021 Annual Report		
·	the roles and responsibilities and safety drills in the	2021 Imital Report		
	Emergency Response Plan for Dam Safety dated July			
	16, 2020.			
5	Provide the timeline for fulfillment of the	2021 Annual Report		
	recommendations of the Dam Safety Management Plan	2021 Annual Report		
	ļ , , , , , , , , , , , , , , , , , , ,			
	dated July 16, 2020.	2021 Amusl Dec		
6	Provide the timeline for eliminating non-conformities	2021 Annual Report		
	analyzed in Table 4.1 "DSMP Gap Analysis" in the			
	Dam Safety Management Plan dated July 16, 2020.	2001		
7	Provide the timeline for fulfillment of the	2021 Annual Report		
	recommendations of the Technical Analysis & Risk			
	Assessment dated July 16, 2020.			

Licence No: 3AM-IQA1626 2020 Annual Report Review

Copies of all documents received during Report review can be accessed through the NWB's Public Registry and FTP site using the following link:

 $\frac{ftp://ftp.nwb-oen.ca/registry/3\%20MUNICIPAL/3A/3AM\%20-\%20Municipality/3AM-IQA1626/3\%20TECH/B\%20GENERAL/2\%20ANNUAL\%20RPT/2020/$ 

If you have any questions, please contact the undersigned at <a href="mailto:assol.kubeisinova@nwb-oen.ca">assol.kubeisinova@nwb-oen.ca</a> or (867) 360 6338 (ext. 31).

Best regards,

Assol Kubeisinova Nunavut Water Board Technical Advisor

Cc: Distribution List – Iqaluit