TYPICAL SANITARY SERVICE RISER

KEY TO NUMBERED PARTS:

- (3) 250 DIA.207kPa BACKING FLANGE HOT DIPPED GALV. SCREWED TO FLOOR RESTORE FLOOR TO EXISTING CONDITION
- (5) FLOOR JOIST- EXISTING
- (6) CAULK WITH SILICON ALL AROUND.
- (8) HEAT SHRINK.
- POLYURETHANE HALF SHELL CUT TO LENGTH AND COATED WITH ASPHALT
- (10) 240mm DIA X 600mm LONG SLEEVE WITH 100mm WIDE COLLAR MADE FROM REEVES BROTHERS INC. COVERLIGHT TL-16

- (16) SANITARY SERVICE 100mm DIA. IPS DR 13.5 WITH 50mm NOMINAL POLYURETHANE AND FACTORY INSTALLED JACKET
- (17) LONG RADIUS 90° ELBOW WITH FACTORY APPLIED POLYURETHANE INSULATION WITH REINFORCED JACKET.
- BUTT FUSION JOINT TO BE MADE BY A QUALIFIED AND LICENSED

RESOLUTE BAY NUNAVUT

UTILIDOR REPAIRS RESOLUTE BAY NUNAVUT



A. D. Williams Engineering Inc. #4903-47 Street P.O. Box 1529 Yellowknife, NT X1A 2P2 (867) 873-2395 (867) 873-2547

Edmonton Office (780) 424-2393 (780) 425-1520 ADWE NO .:

DESIGN BY:	רכ	DATE: 03.07.29	
	DFG	SCALE: N.T.S.	
DRAWN BY:	רכ	DWG NO:	REV NO:
	DFG		A
APPROVED BY:	BFG	13K 14	A
	ט ט		