

1. GENERAL

- .1 Coordinate main service with NPC and installation of new service feeders, meter base, enclosed circuit breakers and splitters for heat trace servicing. Pay for all utility costs from a power cash allowance of \$10,000 per service drop.
- .2 Where it is specified that an allowance is to include both supply and installation costs, such allowances shall cover the cost of materials and equipment delivered and unloaded at the site and all applicable tax. The Contractor's handling cost on the site, labour, installation costs and other expenses except overhead and profit which shall be included separately in the Contract Price.
- .3 Allowances for independent inspection and testing shall cover the cost of such services as provided by the independent testing agency only. The Contractor's cost for labour, overhead and other expenses shall be included separately in the Tender Price and not in the allowance.
- .4 If the cost of the work is covered by allowances, when determined is more or less than the allowance, Change Order shall adjust the Contract Price accordingly.
- .5 The Contractor shall cause the work covered by allowances to be performed for such amounts and by such persons as the Engineer may direct.
- .6 The Engineer shall authorize expenditures from allowances in writing. Trade documents and refunds shall be credited to the Owner, only cash discounts (if any) on account paid by the Contractor before net due date being retained by the Contractor.
- .7 Ensure that allowance and other costs required in connection therewith are included only once in the Contract Price.
- .8 Progress payments for work and material authorized under cash allowance will be made in accordance with the Terms of Payment of Contract.

END OF SECTION 01020