Appendix L

List of Waste Disposal Activities

Year: 2010 (As of issuance of licence: Aug. 4, 2010.)

Reference: 3BC-ALT1015, Part B, 1a.

Main Station Landfill:

-Deposition of non-hazardous incinerator ash and all acceptable materials to site.

Millionaire's Dump:

-Deposition of non-hazardous metallic and bulky waste materials.

Battery Dump:

- No waste was deposited at this site.
- No waste deposition is allowed at this site.

Dump #3:

- No waste was deposited at this site.
- No waste deposition is allowed at this site.

Landfarm:

-196 cubic meters of fuel contaminated gravel was placed into the Landfarm Facility in 26 October 2011 during clean up of a September spill event at the Stand-By Power Plant (Building 146, Lat. 82°26'50"; Long -62°20'40"), as per Part J, Item 8. A Nunavut Water Board/INAC inspector (P. Kusugak) was promptly contacted of the event, as per Part G, Item 4.

Hazardous Waste Backhaul from CFS Alert: 72 Drums, includes:

- Battery Ashes in Drums to 8 Wing Trenton;
- Waste chemicals to 8 Wing Trenton;
- Used Batteries to 8 Wing Trenton.

Attached is a statement from the disposal contractor (Direct Line Environmental Corp.) ensuring all hazardous waste was collected from 8 Wing Trenton and properly disposed, including final disposal location.

3BC-ALT1015-2010-AppendixL.pdf

1



1070 Toy Avenue, Pickering, ON L1W 3P1

Telephone: 905-509-2460 Or 1-800-541-2527 Fax: 905-428-6007

CERTIFICATE OF DISPOSAL

Service Date: January 31, 2011

Material received from: **CRB Trenton** 27 Alert Blvd (Bldg 165) Trenton, Ontario K0K 3W0

Have been received at:

Direct Line Environmental Services Inc. Receiver No. A680301 1070 Toy Avenue

Pickering, Ontario L1W 3P1

In accordance with all Ministry of Environment Regulations and current LDR requirements.

Material Disposal:

Process	Destination	Quantity
112 C Phosphoric Acid Neutralization to Water Treatment	Direct Line	2 drums
Non Hazardous- battery ash Stabilization to Landfill	Direct Line Landfill	41 drums
Recycling – batteries	RMC	29 drums

3BC-ALT1015-2010-AppendixL.pdf

2