



ᓄᓇᓂᓪ ᐃᓕᓂᓪᓴᓪ ᑲᓂᓕᓪᓴᓪ
NUNAVUT WATER BOARD
NUNAVUT IMALIRIYIN KATIMAYINGI
OFFICE DES EAUX DU NUNAVUT

File: 3BC-ING0712

November 08, 2013

The following summary report is a reflection and review of all information received as of Oct 28, 2013 from the Licensee and INAC inspectors with regards to Licence 3BC-ING0712. This was completed in response to cancellation request application for the Turaavik Outpost Camp Licence which expired on July 31, 2011

Subject: Assessment of Administrative Compliance for the Cancellation of Municipal Water Licence 3BC-ING0712

The Nunavut Water Board (“NWB” or “Board”) has taken the opportunity to summarize the information regarding water Licence 3BC-ING0712, to review the public registry files and confirm that the following information is on file with the NWB, with respect to the requirements of the Licence.

Licence

Licence No: 3BC-ING0712
License issued: July 06, 2007
Expiry Date: September 30, 2012

SCOPE, DEFINITIONS AND ENFORCEMENT

INAC Inspection Reports/Communications:

Date of Inspection or Letter:	Received by NWB:
Aug 6, 2011	June 26, 2012

Issues raised in the 2011 inspection report:

- Camp was inactive during time of inspection and open burning had occurred at the site;
- A general clean-up of the camp is required with materials brought back to Baker Lake for disposal.
- Fuel drums present on site.

GENERAL CONDITIONS

Water Use

Fee:

Year Reporting:	Received:	Comments on the Report:
2007	April 4, 2007	Application Fee and Water use fee (WUF)
2008	Not received	Outstanding WUF \$30
2009	Not received	Outstanding WUF \$30
2010	Not received	Outstanding WUF \$30
2011	Not recieved	Outstanding WUF \$30
2012	Not received	Outstanding WUF \$7.15 (from July 6 to Sept 30, 2012)

Annual Report:

Year Reporting:	Received:	Comments on the Report:
2007	Not received	
2008	Not received	
2009	Not received	
2010	Not received	
2011	Not received	
2012	Okay	An annual report with no date was received by NWB on November 22, 2012. E-mail on file indicating no activity on site.

WASTE DISPOSAL

Noted on the 2011 inspection report that a general clean-up of camp is required with all material brought back to Baker Lake for disposal and open burning occurring on site during time of inspection.

CAMPS, ACCESS INFRASTRUCTURES AND OPERATIONS

No issues identified

MODIFICATION

No issues identified

SPILL CONTINGENCY PLANNING

An addendum to the spill plan was required within 30 days of the issuance of the Licence.

ABANDONMENT AND RESTORATION

Review of file history and current application appears there are existing camps and facilities. Clean-up of site is required; correspondence from the proponent attributes the state of the site to influences from surrounding and neighboring camps.

ANY OTHER RELEVANT LICENSING INFORMATION

- No application form to cancel application filled out by proponent.

Prepared by:

Erik Skiby
Assistant Technical Advisor
Nunavut Water Board

