



NWB Tools

Megan Porter <megan.porter@nwb-oen.ca>

[Licensing] 3BC-NWT1113- Expired

Andrew Keim <Andrew.Keim@aandc-aadnc.gc.ca>

Wed, Jan 21, 2015 at 1:39 PM

To: Tamara.VaDyck@dcc-cdc.gc.ca

Cc: Erik Allain <Erik.Allain@aandc-aadnc.gc.ca>, phyllis.beaulieu@nwb-oen.ca

Tamara Van Dyck, Director General Military Engineering
Defence Construction Canada
AECOM Canada Ltd.
National Defence Headquarters
101 Colonel By Drive, Ottawa, ON K1A 0K2
Tamara.VaDyck@dcc-cdc.gc.ca

The Field Operations Unit of Aboriginal Affairs and Northern Development Canada is currently engaged in conducting our annual Risk Prioritization Exercise in preparation for the 2015 field season.

It has come to our attention that the above noted Water license for work conducted between 2011 and 2013 has expired. A review of the file submissions is unable to produce either an application for renewal or an application for cancellation of the expired License. It is AANDC's understanding that the above noted license was replaced by the Nunavut Water Board with an annual Authority without a License (8WLC-NWT1415) however the final disposition of the expired license must still be addressed.

In addition to the enclosed assessment form to be completed and returned to our offices by March 31st 2015, I have included a copy of your Water License . I appreciate your cooperation as we move ahead with this file.

If you have any questions or concerns please do not hesitate to contact myself or the Manager of Licensing at the Nunavut Water Board, Phyllis Beaulieu Manager of Licensing Nunavut Water Board. Licensing@NWB-OEN.CA

Thank you in advance for your continued cooperation,

Respectfully,

Andrew Keim
Water Resources Officer
Field Operations Unit
Aboriginal Affairs and Northern Development Canada
Nunavut Regional Office
P.O. Box 100
Iqaluit, Nunavut X0A 0H0
Andrew.Keim@aandc-aadnc.gc.ca
Phone: (867) 975-4289
Fax: (867) 979-6445
B.B (867) 222- 6488

2 attachments**2015 PROJECT ASSESSMENT CHECKSHEET.DOCX**



176K



IQALUIT-#479734-v1-110818_3BC-NWT1113_LICENSE-OESE_PDF.PDF

174K