



P.O. Box 119
GJOA HAVEN, NU X0B 1J0
TEL: (867) 360-6338
FAX: (867) 360-6369

ᓄᓇᓂᓪ ᐃᓕᓕᓂᓪ ᑲᑎᓕᓂᓪ
NUNAVUT WATER BOARD
NUNAVUT IMALIRIYIN KATIMAYINGI

NWB File No: Unlicensed

February 26, 2001

To: Distribution List

Re: Cape Dorset Water Supply Pipeline Replacement

On February 16, 2001, the Nunavut Water Board received drawings and specification with regards to the Cape Dorset Water Supply Pipeline Replacement from Gary Strong of Dillon Consulting, for our review and comments.

Due to the fact that the Hamlet of Cape Dorset does not have a water licence, the Nunavut Water Board cannot review or provide comments at this point, but has brought the matter to the attention of the DIAND Inspector.

For your information, only copies of the cover letter from Dillon Consulting and the drawings are being forwarded to your office along with this letter. The "Construction Tender & Contract Specifications" can be forwarded to your office upon your request.

Sincerely,

Rita Becker
Licensing Administrator

cc. Philippe Lavallee, DIAND Inspector
Greg Cook, DIAND-YK
Paul Smith, DIAND-Iqaluit
Paula Pacholek, EC
Gladys Joudrey, NIRB
Chris Nichols, DSD
Jordan deGroot, DFO