



P.O. Box 119
GJOA HAVEN, NU X0B 1J0
TEL: (867) 360-6338
FAX: (867) 360-6369

ᓄᓇᓂᓪ ᐃᓕᓕᓂᓪ ᑲᑎᓕᓂᓪ
NUNAVUT WATER BOARD
NUNAVUT IMALIRIYIN KATIMAYINGI

NWB File No: Unlicensed

February 26, 2001

Hayward Sims
Senior Administrative Officer
Municipality of Cape Dorset
P.O. Box 30
Cape Dorset, NU X0A 0C0

Re: Cape Dorset Water Supply Pipeline Replacement

Dear Mr. Sims:

On February 16, 2001, the Nunavut Water Board received drawings and specification with regards to the Cape Dorset Water Supply Pipeline Replacement from Gary Strong of Dillon Consulting, for our review and comments.

Due to the fact that the Hamlet of Cape Dorset does not have a water licence, the Nunavut Water Board cannot review or provide comments at this point, but will send a copy of this letter and the drawings and specifications to the attention of the DIAND Inspector.

I am attaching a copy of our application form and supplementary questionnaire (both available in Inuktitut upon request) to this letter. For an application to be deemed complete, both of these items need to be filled out. As well, a \$30 application fee must be submitted payable to the Receiver General for Canada, and there must be a short summary of the application in both English and Inuktitut. If you would like to have the forms sent by e-mail, please contact me at rbecker@polarnet.ca. If you have any questions, please do not hesitate to contact our office.

Sincerely,

Rita Becker
Licensing Administrator

cc. Philippe Lavallee, DIAND Inspector
Gary Strong, Dillon Consulting
Mr. Balijinder Brar, Project Officer, Public Works, Pond Inlet