

P.O. Box 119 GJOA HAVEN, NU X0B 1J0 TEL: (867) 360-6338 FAX: (867) 360-6369

NUNAVUT WATER BOARD NUNAVUT IMALIRIYIN KATIMAYINGI

File: NWB3GJO0409

July 26, 2006

Joe Murdock Technical Advisor Nunavut Water Board

Subject: July 17, 2006 Landfill site visit

Dear Joe,

On July 17, 2006 NWB has sent me on a field trip to the Gjoa Haven land fill to observe problems the landfill is going through. Attached here is the review of the Site Map and photos taken during the site visit. The photos are focused on what the main problems with the Landfill.

KEY: Numbers = Picture #

P= Problem S= Solution

In understanding where the pictures were taken please refer to the site map.

- 1, 2, 3) Entrance of Dump
- P) Garbage left outside of landfill
- S) Remove garbage into landfill
- 4) Berm line dump
- P) Waste along Berm line
- S) Have hamlet staff physically put waste from outside of landfill and put in landfill
- 5, 6, 13-18) Ponding through out the landfill
- P) Water on the berm erodes the berm and ponded water escaped
- S) Remove the water that is collected
- 7-11) South end Breach (run-off)
- P) Open fence, run-off water down towards the ocean
- S) Fence off the missing portion, fill in breach in berm, and ensure that the berm is not washed out by snowmelt (remove snow)
- 12) Soil pile
- P) Soil is there to direct water
- S) Flow or material to fill in berm
- 19) Burnt waste along fencing
- P) Outside of fence
- S) Remove to inside fence
- 20, 21) Oil drum and Chemical spill
- P) Chemical not stored and handled properly

- S) Store to proper location, clean spill
- 22) Drum storage not in Berm
- P) Appears to be no berm
- S) Build one or bring to inside of berm
- 23) Propane tank
- P) Not properly stored
- S) Propane tanks must be organized
- 24-28) Fuel spill Disposal site
- P) Berms not permanently held together, wind erosion, waste was remaining, plastic cap was not held in well
- S) Cover waste; armoring berm wall. Plastic is tightly together
- 29) Ski-doo near pond
- P) Improper storage
- S) Remove to Bulk metals

Sincerely,

Albert Anguttitauruq Student Technical Assistant