

ዋ∩ናΓ▷ና ዻ፟~ውላናጋ፦ሊጕዣናር ♭∩∟ጕ፣ኆላጕና KITIKMEOT HEALTH BOARD

Cambridge Bay, Northwoot Torritories, Canada XOC 0C0 Tel. (403) 963-7328 Fax. (403) 963-2253

PROVIDING

HEALTH SERVICES

TO THE

COMMUNITIES OF

THE KITIKMEOT REGION,

BATHURST INLET

BAY CHIMO

CAMBRIDGE BAY

COPPERMINE

GJÓA HAVEN

HO! MAN

PELLY BAY

SPENCE BAY

。セコットリシュ

ቀያ ቀጋ' "ዶ,"

∇₽4,∪⊳4ε

יורויר ∆_יסדרווי

عود ر. ، عاد

دلاكماء

AN INCOM

ייכינגי

מיכיגים

۵۳،۲۰۵۳

מי∧~ילמ•

C¬,44.

KITIKMEONOT

ANNIAKTOLIGINIKMOT

IKAYOKTIOYOT

KITIKMENT NINNANGANI

KINGAOK

OMINOMAKTOK IKALUKTUTIAK

KUGI UKTUK

OKHOKIOK


ULUKHAKTOK

AKVILIKYOAK

TALOKYOAK

May 19, 1998

Maria Limousin
Senior Administrative Officer
Hamlet of Pelly Bay
Pelly Bay, NT



Re: Municipal Services

Inspections were conducted of Pelly Bay's municipal services, May 12 to 14, 1995, In accordance with the Public Health Act of the Northwest Territories. The following observations and recommendations are offered for your information and action...

Community Water Supply

As discussed, the owner/operator is required pursuant to the Public Water Supply Regulations to submit a monthly water sample for bacteriological analysis. The nurse in-charge would be pleased to send this sample to Stanton Regional Hospital with their biologicals on Tuesday but would ask that it be received at the health control before noon. I would recommend that the sample be taken from the water truck as it is representative of the quality of water being delivered. A year supply of sample containers and forms were left with you for this purpose.

The regulations state that "the application of chlorine be sufficient to provide 0.2 mg/l of free chlorine after a thorough mixing of the chlorine with water and twenty minutes of contact time after the mixing". The chlorine residual must be monitored and recorded in a log book each day. At the time of Inspection, no chlorine residual could be detected in the water system. Please ensure that this deficiency is rectified as soon as possible.

Solid Waste Disposal

It would appear that the solid waste disposal cite is being well managed. Once the snow cover is gone, I would recommend that the wastes be compacted and backfilled with available cover material. Consideration should be given to installing a fence to control blowing paper.

Sewage Laggon

Due to snow and ice cover, the operation of the sewage lagoon could not be assessed. A re-inspection will be conducted during the summer months.

Day Care Centre

I inspected the day care centre in company with the fire marshal on May 12th and am pleased to report that the physical requirements of the Child Day Care Standards Regulations have been met. Conditional approval is consequently granted subject to a satisfactory compliance inspection of the operational requirements when I return to Polly Bay this summer.

Airport Terminal Building

At the time of inspection, no disposable paper towels were available in the men's washroom. Please ensure a supply of paper towels, dispensed soap, and toilet tissue at all times.

Rables Lay Vaccinator Program

I have ordered this year's rabics supplies for the Kitikmsot region. Please let me know if your lay vaccinator requires any vaccine, syringes, sharps containers, tags or certificates.

Should you have any queries or comments regarding this correspondence or the environmental health program, do not hesitate to contact me at (867) 920-6529.

Robert Phillips, CPHI(C)

, MA DO.

Senior Environmental Health Officer

c.c. MACA, Cambridge Bay