



NWB Tools

Robin Ikkutisluk <[robin.ikkutisluk@nwb-oen.ca](mailto:robin.ikkutisluk@nwb-oen.ca)>

---

## [Licensing] Inspection the liner of the Qikiqtarjuaq Water Reservoir; Renewal application of WL 3BM-QIK 0712

---

Roy, Bhabesh <[BRoy@gov.nu.ca](mailto:BRoy@gov.nu.ca)>

Tue, Jul 29, 2014 at 1:37 PM

To: "Karén Kharatyan ([karen.kharatyan@nwb-oen.ca](mailto:karen.kharatyan@nwb-oen.ca))" <[karen.kharatyan@nwb-oen.ca](mailto:karen.kharatyan@nwb-oen.ca)>, "[licensing@nwb-oen.ca](mailto:licensing@nwb-oen.ca)" <[licensing@nwb-oen.ca](mailto:licensing@nwb-oen.ca)>

Cc: "Boyle, David" <[DBoyle@gov.nu.ca](mailto:DBoyle@gov.nu.ca)>, "Constantineau, Micheal" <[MConstantineau@gov.nu.ca](mailto:MConstantineau@gov.nu.ca)>, "Ruediger, Ralph" <[RRuediger@gov.nu.ca](mailto:RRuediger@gov.nu.ca)>

Hi Karen,

Hamlet of Qikiqtarjuaq received the new pump to drain out their water Reservoir just this morning. It is too late to start the draining work, inspect the liner and fill the reservoir back this summer. Also we do not know yet if the new pump works well. Therefore, It is deferred to the next year 2015.

If you have any question or concern, please let me know.

Thanks.

Bhabesh

**Bhabesh Roy, [M.A.Sc.](#), P.Eng.**

Municipal Planning Engineer

Community Government Services

Baffin Region, Government of Nunavut

P.O.Box 379, Pond Inlet, X0A 0S0

Ph-[867 899 7314](tel:867-899-7314)

Fax-[867 899 7328](tel:867-899-7328)

E-mail: [broy@gov.nu.ca](mailto:broy@gov.nu.ca)