



WATER LICENCE INSPECTION FORM

☒ Original
☐ Follow-Up Report

Licensee		Licensee Representative	
Economic Development and Transportation Government of Nunavut		Todd Mckay	
Licence No. / Expiry		Representative's Title	
3BM-YRB0308		Director of Nunavut Airports	
Land / Other Authorizations		Land / Other Authorizations	
Date of Inspection		Inspector	
07/10/2015		Atuat Shouldice	
Activities Inspected			
<input type="checkbox"/> Camp	<input type="checkbox"/> Drilling	<input type="checkbox"/> Mining	<input type="checkbox"/> Construction
<input type="checkbox"/> Roads/Hauling	<input checked="" type="checkbox"/> Other: Sewage Lagoon	<input type="checkbox"/> Other: Water use	<input type="checkbox"/> Reclamation
<input type="checkbox"/> Fuel Storage			

Conditions:		A - Acceptable	C - Concern	U - Unacceptable	NA – Not Applicable	NI – Not Inspected		
Water Use	Condition	Comment	Site Conditions	Condition	Comment	Haz/Mat Management	Condition	Comment
Intake/Screen	NA		Water Management Structures	A		Storage	A	
Flow Measure. Device	NA		Culverts / Bridges	A		Spills	C	
Source:	NA		Drainage	A		Spill Plan	NI	
Water Use:	NA		Erosion / Sediment	C	1			
Recirculation (y /n)	NA		Mitigation Measures	A		Administrative		
			Reclamation Activities	A		Records	A	
			Materials Storage	A		Reports	C	
Waste Disposal			Signage	A		Plans	A	
Waste Water	NI					Notifications	C	
Solid Waste	NI		Monitoring			Other		
Hazardous Waste	NI		Sample Collection / Analysis	A				
Sewage	C	1						
*The number in the comments field will correspond with specific comments provided below.								
Samples taken by Inspector:			Location(s): Resolute bay					
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No								

SECTION 1	<input type="checkbox"/> Comments (s. __)	<input type="checkbox"/> Non-Compliance with Act or Licence (s. __)	<input type="checkbox"/> Action Required (s. __)
An Inspection was conducted on July 10 th 2015 of water licence 3BM-YRB0308. Licence has been expired since 2008.			
SECTION 2	<input checked="" type="checkbox"/> Comments (s. __)	<input type="checkbox"/> Non-Compliance with Act or Licence (s. __)	<input type="checkbox"/> Action Required (s. __)
Sewage/ Erosion 1			
With upgrades to the sewage plant being delayed and no confirmed dates being set, The Airport Lagoon is still in use, The lagoon supports the Airport and adjacent facilities. With capacity issue being noted in past inspection, the lagoon continues to over top each year, discharging raw sewage in to the environment. Signs of erosion are present in the area where the lagoon overtops. (Action Item 1)			
SECTION 3	<input type="checkbox"/> Comments (s. __)	<input type="checkbox"/> Non-Compliance with Act or Licence, (s. __)	<input checked="" type="checkbox"/> Action Required (s. __)
Action Item 1			
A plan must be submitted to the Inspector to address issues identified below:			
<ul style="list-style-type: none">Over topping/ capacity of lagoonErosion preventionRenew licence			
The inspector requests that the proponent provide details of how these issues will be addressed and a timeline for the work to be done. It is unacceptable that the Airport facility is run without a valid water license. Section 11 of the Nunavut Waters and Nunavut Surface Rights Tribunal Act states that:			
“no person shall use, or permit the use of water in Nunavut except in accordance with the conditions of a license.”			
It is imperative that the proponent immediately initiating the process of applying for a Water License that will cover the			



scope of the current Airport activities that relate to the use of water and deposit of waste. If action is not taken to address the issues noted above, further enforcement action will be taken.

Licensee or Representative	Inspector's Name Atuat Shouldice
Signature	Signature <i>Atuat Shouldice</i>
Date	Date 12/22/2015

Office Use Only:	Follow-up report to be issued by Inspector	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
------------------	--	---