

Bathurst Inlet Lodge Ltd

YEAR BEING REPORTED: 2017

The following information is compiled pursuant to the requirements of **Part B, Item 1** of Water Licence (license number) issued to Bathurst Inlet Lodge

i)- iii) tabular summaries of all data generated under the “Monitoring Program”; monthly and annual quantities in cubic metres of freshwater obtained from all sources; monthly and annual quantities in cubic metres of each and all wastes discharged;

Attached are results for Monitoring station **XXX-1, XXX-2, XXX-3 and XXX-4**, as well as detailed chemical, physical and biological analysis required at **XXX-2** and **XXX-4** (for the months of May to August, inclusive)

Month Reported	Quantity of Water Obtained from all sources	Quantity of Sewage Waste Discharged
January	0	0
February	0	0
March	0	0
April	0	0
May	0	0
June	9.5	.3375
July	9.5	.3375
August	0	0
September	0	0
October	0	0
November	0	0

December	0	0
ANNUAL TOTAL	19.0	0.68

Please indicate volumes in cubic metres - 1 cubic meter equals 1000 litres

- a summary of modifications and/or major maintenance work carried out on the Water Supply and Waste Disposal Facilities, including all associated structures and facilities;

There was not modifications and or major maintenance work carried out on the Water supply and Waste Disposal Facilities.

- a list of unauthorized discharges and summary of follow-up action taken;

None

- a summary of any abandonment and restoration work completed during the year and an outline of any work anticipated for the next year;

None

- a summary of any studies requested by the Board that relate to waste disposal, water use or reclamation, and a brief description of any future studies planned;

1.

none requested

- any other details on water use or waste disposal requested by the Board by November 1st of the year being reported; and

None

- updates or revisions to the approved Operation and Maintenance Plans.

None

ADDITIONAL INFORMATION THAT THE LICENSEE DEEMS USEFUL:

The lodge operated for two weeks in 2016 and we hope to operate for 3 or 4 in 2017.

FOLLOW-UP REGARDING INSPECTION/COMPLIANCE CONCERNS:

Areas identified in last report were carried out. Specifically:

- 2015 report was submitted
- no Garbage from the lodge was deposited on "Garbage Island"
- Hazardous materials would be backhaul to YK.
- The use of a new route to the airstrip was investigated and it was determined that more damage would be done than using the existing route. It should be noted the trail in use is primarily a community trail and only used 6 - 10 times / yr by the lodge.
- the new sewage location and burn locations were activated as per the inspectors request.

Bathurst Inlet Lodge.