



P.O. Box 119
GJOA HAVEN, NU X0B 1J0
TEL: (867) 360-6338
FAX: (867) 360-6369

ᓄᓇᓂᓪ ᐃᓕᓕᓂᓪ ᑲᑎᓴᓪ
NUNAVUT WATER BOARD
NUNAVUT IMALIRIYIN KATIMAYIT
OFFICE DES EAUX DU NUNAVUT

File: **3BC-EUR0611/TR/B2**

June 25, 2012

Mr. Carl Carroll
Property Management Divisions Assets
Contracting & Environ Management Directorate
Finance and Corporate Branch
Environment Canada
335 River Road
Ottawa, ON K1A-0H3
E-mail: carl.carroll@ec.gc.ca

**Subject: Submission of the 2011 Annual Report for the “Eureka Weather Station”
Project; Licence No. 3BC-EUR0611**

Dear Mr. Carroll;

The Nunavut Water Board (“NWB”) has completed a technical review of the 2011 Annual Report for the above-mentioned Project that was received on March 28, 2012.

The Eureka wastewater effluent 2011 sampling identified Total Suspended Solids (TSS), pH, iron and manganese still exceeding the Territorial guidelines. These parameters exceeded the guidelines in 2009, 2010 as well.

For all of these parameters, the causes of elevated levels should be studied and identified, and actions should be taken to bring the wastewater lagoon effluent concentrations in compliance with guidelines.

Should you have any questions, please feel free to contact the undersigned at (867) 360-6338 Ext. 30 or k.kharatyan@nunavutwaterboard.org, at your earliest convenience.

Yours truly,

Original signed by:

Karen Kharatyan
Technical Advisor

cc: Distribution List – Qikiqtani