



ᓄᓇᓂᓪ ᐃᓕᓕᓂᓪ ᑲᑎᓕᓂᓪ  
NUNAVUT WATER BOARD  
NUNAVUT IMALIRIYIN KATIMAYINGI  
OFFICE DES EAUX DU NUNAVUT

File No.: 8BC-BTN1819

February 12, 2019

Matthew Hamp  
City of Iqaluit  
Box 460, Iqaluit, Nunavut  
X0A 0H0

Dan Elliot  
Field Operations Lead  
Concentric Geosciences Inc.  
2327 St Laurent BLVD., Unit 100  
Ottawa, Ontario K1G 4J8

Email: [m.hamp@city.iqaluit.nu.ca](mailto:m.hamp@city.iqaluit.nu.ca)

Email: [dan@concentricgeo.com](mailto:dan@concentricgeo.com)

**RE: NWB Technical Review of Environmental Protection Plan for the Bridge to Nowhere – Repair to Abutments Project; Water Licence No. 8BC-BTN1819.**

---

Dear Mr. Hamp and Mr. Elliot:

The Nunavut Water Board (NWB) has completed a technical review of the Environmental Protection Plan (EPP) submitted on February 8, 2019.

On February 11, 2019, the NWB acknowledged receipt of the EPP and provided it to the Iqaluit distribution list for information. No comments have been received to date.

The technical review of the EPP, found that the information addresses the requirements of the Licence.

The technical review identified the following issue(s):

- SECTION 3, APPLICABLE LEGISLATION/LEGAL REQUIREMENTS:
  - The third bullet on page 2 reads “Nunavut Information Review Board”. This should read “Nunavut Impact Review Board”.
- SECTION 6, SPILL AND ENVIRONMENTAL EMERGENCY RESPONSE PLAN:
  - The last box in the flow chart on page 6 reads “Nunavut Water Board Inspector”. This should read “Crown-Indigenous Relations and Northern Affairs (CIRNAC)”. The Nunavut Water Board does not hold jurisdiction for Water Licence inspection or compliance. That jurisdiction rests with CIRNAC.
- APPENDIX B, FIGURE C2:
  - The ‘Light Duty Silt Fence Barrier’ diagram shows the fence installed into a trench below the channel. Earlier in the EPP, on page 3, it states that construction is

intended to occur when the 'water course is frozen'. If construction occurs while the channel is frozen to the bottom, the NWB recommends considering an alternate to installing the silt fence into a trench below the channel.

Should you have any questions, please feel free to contact me, Dave Baines, at (867) 360-6338 (extension 29), at your earliest convenience.

Sincerely,

---

Dave Baines  
Nunavut Water Board,  
Technical Advisor

Cc: Distribution List – Iqaluit