

Appendix L

Site layout map

WATER QUALITY MONITORING


NANISIVIK MINE, NUNAVUT

BREAKWATER RESOURCES LTD.

Client:

Job No.:	121810952	Dwg. No.:	
Scale:	1 : 30,000		
Date:	2013 02 19		
Dwn. By:	JL		
App'd By:	MS		

A-2



LEGEND:

-  ROAD
 GROUND CONTOUR
 (50 m INTERVAL)
 SHOULDER, DRAINAGE, STREAMS
 INTERMEDIATE DRAINAGE
 HIGH TOP LINE - SURVEYED
 TOP OF BANK
 PRE-LINE
 EXENT OF UNDERGROUND
 WORKINGS
 MINING AREA
 ADIT, PACE
- * TWA-35
 WATER SAMPLING LOCATION