

TECHNICAL REVIEW			
LICENCE No.:	NWB1NAN0208		
DOCUMENT:	Get from FTP SITE		
CONDITION: Part:	G	Item:	3 Complete Closure and Reclamation Plan

CONTACT INFORMATION	
Murray Markle	Robert Carreau
Site Manager	Corporate Manager, Environmental Affairs
Nanisivik Mine	Breakwater Resources Limited
P.O. Box 225	Suite 2000, 95 Wellington Street West
Nanisivik, NU	Toronto, ON. M5J 2N7
X0A 0X0	
Phone: (867) 436 - 7376	Phone: (416) 363-4798 (ext 271)
Fax: (867) 436 -7435	FAX: (416) 363-1315
mmarkle@nu.breakwater.ca	bcarreau@breakwater.ca

Date	Reviewed or Updated by:	Final Action:
20-May-04	Patrick Duxbury	PTR completed

Document Information submitted by Licensee:				Supplemental Information Reviewed: (Inspection/Compliance Reports and
Report	Received	Reviewed by	Completed	
Nanisivik Mine - 2003 Annual Water Report	pre April 2004	Patrick Duxbury, RC		

Document Background