



ᓄᓇᓂᓪ ᐃᓕᓕᓂᓪᓐ ᑲᓂᓕᓂᓪᓐ
NUNAVUT WATER BOARD
NUNAVUT IMALIRIYIN KATIMAYINGI
OFFICE DES EAUX DU NUNAVUT

May 8, 2015

Mr. Johan Skoglund
Group Manager Environment
Nyrstar
2840-650 W. Georgia Street
P.O. Box 11552
Vancouver, BC V6B 4N8
Email: Johan.skoglund@nyrstar.com

SUBJECT: 1AR-NAN1419 Receipt of 2014 Annual Report

Dear Mr. Skoglund:

The Nunavut Water Board (NWB) acknowledges receipt, on March 30, 2015 of the 2014 Annual Report for the Nanisivik Mine. Included with the report were the various management plans as listed in your cover letter (attached).

For convenience, below is a Table indicating all submissions required under water licence 1AR-NAN1419. Please note that the 2014 Geotechnical Inspection Report has been received and will be uploaded to our ftp site as soon as possible.

Anyone wishing to provide comments on any portion of the annual report, please do so by return email to licensing@nwb-oen.ca

Licence Terms and Condition	Description	Board Decision after Public Review
Part I, Items 6 and 7	2014 Annual Geotechnical Inspection Report	Acceptance
Par D, Item 12	<i>Nanisivik Mine Contaminated Soil Remediation 2014 Progress Report</i> , dated March 2015	Acceptance
Part B, Item 2	<i>2014 Annual Water Quality Monitoring Report</i> , dated March 20, 2015	Acceptance
Part F, Item 11 (b)	<i>Update to Soil Quality Remediation Objectives for the Former Nanisivik Mine</i> , dated March 2015	Acceptance



Sincerely,

Original signed by:

Phyllis Beauleu
Manager of Licensing
Nunavut Water Board

Cc: Nanisivik Distribution