

Appendix I: Picture Library of Individual Sites

Below are photos of all the openings listed above as of May 7 to 8, 2002 (except where noted). These are included to allow for a better understanding of each opening and the remedial actions required.

Lower Adit




00 Portal




01 Portal





09 South Portal



17 North Portal




39 Portal




Being backfilled



**Being backfilled
Showing remaining opening**



88 Portal



K Baseline Portal



Ocean View Portal




Area 14 Portal


Access to Area 14 is currently unavailable due to snow buildup on the road.

Shale Hill Raise

Summer 1999



Current



Ocean View East Raise



Ocean View West Raise



Area 14 Raise


Access to Area 14 is currently unavailable due to snow buildup on the road.


West Pit Highwall




East Pit Highwall

**General view showing East Pit
and East Trench**






East Trench Highwall



Ocean View Pit Highwall

Looking South



Appendix II: Map showing location of openings to surface

