
TECK COMINCO LTD.

Decommissioning of Dock Facilities at Polaris Mine
Little Cornwallis Island, Nunavut

## APPENDIX B

Photographs



Photograph No. 1: Quarry face in Little Red Dog Quarry (August 17, 2000).



Photograph No. 2: View of shoreline to north of dock, from north end of dock (August 17, 2000).



**Photograph No. 3:** View of area between dock and process barge (August 18, 2000).



**Photograph No. 4:** View of shoreline to south of dock, from the deck of the vessel "Federal Baffin" (August 17, 2000).



**Photograph No. 5:** View of shoreline looking north at Station 1800 N. The beach is natural at this location, and is comprised of gravel with a mean size of about 10 mm (August 19, 2000).



**Photograph No. 6:** View of shoreline looking north at Station 1700 N. The fill, which is tapering out at this station, is about a 300 mm minus material. (August 19, 2000).



Photograph No. 7: View of shoreline looking south at Station 1700 N. (August 19, 2000).