



INSPECTION FORM

☒ Original  
☐ Follow-Up Report

Licensee	Licensee Representative
Teck Resources Limited.	Bruce Donald (bruce.donald@teck.com)
Licence No. / Expiry	Representative's Title
1AR-POL1531	Manager, Dormant Properties, Environment
Land / Other Authorizations	
68h/8-1-3, 68h/8-2-2	
Date of Inspection	Inspector
29 JULY 2017	Justin HACK
Activities Inspected	
<input type="checkbox"/> Municipality <input type="checkbox"/> Roads/Hauling	<input type="checkbox"/> Drilling <input checked="" type="checkbox"/> Other: Camp
<input type="checkbox"/> Mining	<input type="checkbox"/> Construction <input type="checkbox"/> Other:
<input type="checkbox"/> Reclamation	<input type="checkbox"/> Fuel Storage

Conditions:	A - Acceptable	C - Concern	U - Unacceptable	NA – Not Applicable	NI – Not Inspected			
Water Use	Condition	Comment	Site Conditions	Condition	Comment	Haz/Mat Management	Condition	Comment
Intake/Screen	NA		Water Management Structures	NA		Storage	NA	
Flow Measure. Device	NA		Culverts / Bridges	NA		Spills	NA	
Source:	NA		Drainage	NA		Spill Plan	NA	
Water Use:	NA		Erosion / Sediment	A				
Recirculation ( y /n)	NA		Mitigation Measures	NA		Administrative		
			Reclamation Activities	A		Records	C	
			Materials Storage	NA		Reports	C	
Waste Disposal			Signage	NA		Plans	NI	
Waste Water	NA					Notifications	NI	
Solid Waste	NA		Monitoring			Other		
Hazardous Waste	NA		Sample Collection / Analysis	NA				
*The number in the comments field will correspond with specific comments provided below.								
Samples taken by Inspector:			Location(s):					
<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No								

SECTION 1	<input checked="" type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Licence	<input type="checkbox"/> Action Required
<b>Inspectors Statement</b>			
On July 29 <sup>th</sup> 2017, a water licence inspection was conducted at the Former Polaris Mine Site, on Little Cornwallis Island in the Qikiqtani Region of Nunavut.			
<b>Water Use:</b>			
No water was being used at the time of the inspection.			
<b>Waste Disposal:</b>			
Possible waste disposal to water is being monitored by Teck Resources Ltd, at Monitoring Station No. 262-7. However, there is no information associated with this licence that shows any discharge records.			
<b>Monitoring:</b>			
No current records of monitoring data are available on the NWB ftp site.			
<b>Land Use:</b>			
No land use activities were occurring on site that required a permit as observed.			

Inspector's Name	
Justin Hack	
Signature	
Date	
September 22, 2017	