



P.O. Box 119  
GJOA HAVEN, NU X0B 1J0  
TEL: (867) 360-6338  
Fax: (867) 360-6369

ᓄᓇᓂᓪ ᐃᓕᓕᓂᓪ ᑲᑎᓕᓪᓴᓂ  
NUNAVUT IMALIRIYIN KATIMAYINGI  
NUNAVUT WATER BOARD  
OFFICE DES EAUX DU NUNAVUT

March 25, 2010

File No: 1AR-POL0311/TR/B3&B6

Bruce Donald  
Environment and Corporate Affairs  
Teck Resources Limited  
Bag 2000  
Kimberley, BC V1A 3E1  
By Email: [Bruce.Donald@teck.com](mailto:Bruce.Donald@teck.com)

Subject: Submission of 2010 1<sup>st</sup> and 2<sup>nd</sup> Quarter Decommissioning and Reclamation Report  
Post-Reclamation Monitoring Report 3<sup>rd</sup> and 4th QUARTER and 2010 Annual Report

Dear Mr. Donald:

The Nunavut Water Board ("NWB") acknowledges receipt of:

**1<sup>st</sup> and 2<sup>nd</sup> Quarter Report received March 15, 2011**

Appendix 1 – Executive Summary in Inuktitut  
Appendix 2 – May 28, 2010 Garrow Lake Water Quality and Stratigraphy Monitoring Results  
Appendix 3 – May 28, 2010 Garrow Lake Field Monitoring Results  
Appendix 4 – 1<sup>st</sup> and 2<sup>nd</sup> Quarter Expenditure Report  
Appendix 5 – CD with electronic version (pdf) of the 2010 1<sup>st</sup> and 2<sup>nd</sup> Quarter Decommissioning and Reclamation Report

**Post-Reclamation Monitoring Report 3<sup>rd</sup> Quarter received March 15, 2011**

Appendix 1 – Executive Summary of Report Translated to Inuktitut  
Appendix 2 – 2010 3<sup>rd</sup> Quarter Garrow Lake Effluent Discharge Monitoring-Azimuth Consulting Group  
Appendix 3 – Garrow Lake Water Column Hydrolab Data from August 2010  
Appendix 4 – Garrow Lake Water August Column Minimum Ice Conditions Monitoring Event Data-August 2010  
Appendix 5 – Monitoring of Other Site Surface Waters & Soil Samples from Former Concentrate Storage Shed  
Appendix 6 – 2010 Site Surveys – Subsidence Area and Marine Foreshore  
Appendix 7 – Annual Geotechnical Inspection Report-Golder Associates  
Appendix 8 – Wind Monitoring from Environment Canada at Resolute Bay  
Appendix 9 – Landfill Thermistor Monitoring Data  
Appendix 10 – Photographs of August 2010 Demobilizing Activities  
Appendix 11 – Estimated Remaining Financial Liabilities  
Appendix 12 – Electronic Copy of Report on CD

**Post-Reclamation Monitoring Report 4<sup>th</sup> Quarter and 2010 Annual Report received March 23, 2011**

Appendix 1 – Executive Summary Translated into Inuktitut  
Appendix 2 – 2010 Update of Reclamation and Monitoring Costs  
Appendix 3 - Garrow Lake Water Column Monitoring Data and Graphs  
Appendix 4 – Garrow Lake Hydrolab Data and Graphs  
Appendix 5 – Electronic Copy of Files on CD

as requirements of Part B, Item 3 & Part B, Item 6 of water license 1AR-POL0311. These submissions have been placed on the NWB public registry and are available from the NWB ftp site.

These reports are forwarded to the distribution list for information only. Anyone wishing to provide comments can do so by return e-mail to [licensingadmin@nunavutwaterboard.org](mailto:licensingadmin@nunavutwaterboard.org)

Sincerely,

*Original Signed By:*

Richard Dwyer  
Licensing Administrator

cc. Qikiqtani Distribution List