




☒ Original  
☐ Follow-Up Report

Licensee			Licensee Representative		
Inukshuk Construction Limited			Marc Losier		
Licence No. / Expiry			Representative's Title		
1BH-CHE1213			Project Manager		
Land / Other Authorizations			Land / Other Authorizations		
Date of Inspection			Inspector		
07/07/2014			Justin HACK		
Activities Inspected					
<input type="checkbox"/> Camp <input type="checkbox"/> Drilling <input type="checkbox"/> Mining <input type="checkbox"/> Construction <input checked="" type="checkbox"/> Reclamation <input type="checkbox"/> Fuel Storage <input type="checkbox"/> Roads/Hauling <input checked="" type="checkbox"/> Other: Records <input type="checkbox"/> Other:					
<b>Conditions:</b> <b>A - Acceptable</b> <b>C - Concern</b> <b>U - Unacceptable</b> <b>NA – Not Applicable</b> <b>NI – Not Inspected</b>					
<b>Water Use</b>		Condition	Comment	<b>Site Conditions</b>	
Intake/Screen	NA			Water Management Structures	NA
Flow Measure. Device	NA			Culverts / Bridges	NA
Source:	NA			Drainage	NA
Water Use:	NA			Erosion / Sediment	NA
Recirculation ( y /n)	NA			Mitigation Measures	NA
				Reclamation Activities	A      1
				Materials Storage	NA
<b>Waste Disposal</b>				Signage	NA
Waste Water	NA				
Solid Waste	NA			<b>Monitoring</b>	
Hazardous Waste	NA			Sample Collection / Analysis	NA
<b>Haz/Mat Management</b> Condition             Comment					
Storage	NA				
Spills	NA				
Spill Plan	NA				
<b>Administrative</b>					
Records	A				2
Reports	A				2
Plans	NA				
Notifications	NA				
<b>Other</b>					
<i>*The number in the comments field will correspond with specific comments provided below.</i>					

SECTION 1	<input checked="" type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Licence	<input type="checkbox"/> Action Required
<p><u>Background</u></p> <p>Water discharge and waste disposal activities took place in August 2014 by Inukshuk Construction Limited as part of the Hydrostatic Testing of the Chesterfield Inlet Fuel Storage Facility. Approximately 2000 m<sup>3</sup> of fresh water was used from a pond located on the north-east side of the tank farm to check the integrity of the tanks. The licensee took a water sample from the tanks before discharge and the discharge criteria met the limits as set out in the Water Licence.</p> <p><u>Inspectors Statement</u></p> <p>On July 7 2014 a water licence inspection was conducted at the Chesterfield Inlet tank farm. Since all water use and waste disposal activities associated with this licence have ceased and the licence is expired, the inspection was focused on determining whether all relevant terms and conditions of the NWB Licence No. 1BH-CHE1213 were met prior to the expiration of the licence.</p> <p><u>Observations</u></p> <ol style="list-style-type: none"> <li>1. An inspection of the effluent discharge location was conducted to determine if the activity was effectively remediated. Observations from this on-site inspection confirm that the licensee has completed restorative work as required by the water licence.</li> <li>2. Records detailing the proper disposal of approximately 1600kg of petroleum waste were submitted to the Inspector upon request after the inspection.</li> </ol>			
SECTION 2	<input checked="" type="checkbox"/> Comments	<input type="checkbox"/> Non-Compliance with Act or Licence	<input type="checkbox"/> Action Required
<p>Based on the evidence made available to AANDC through correspondences, records, and site inspections, no concern with the site was noted.</p>			

Inspector's Name
Justin Hack
Signature

Date
August 19, 2014