



WATER LICENCE INSPECTION FORM

☒ Original
☐ Follow-Up Report

Licensee			Licensee Representative										
Government of Nunavut Community and Government Services													
Licence No. / Expiry			Representative's Title										
1BR-CIL1217													
Land / Other Authorizations			Land / Other Authorizations										
Date of Inspection			Inspector										
04/07/2014			Justin HACK										
Activities Inspected													
<input type="checkbox"/> Camp			<input type="checkbox"/> Drilling		<input type="checkbox"/> Mining		<input type="checkbox"/> Construction		<input type="checkbox"/> Reclamation		<input type="checkbox"/> Fuel Storage		
<input type="checkbox"/> Roads/Hauling			<input type="checkbox"/> Other:		<input checked="" type="checkbox"/> Other: Landfarm								
Conditions:			A - Acceptable		C - Concern		U - Unacceptable		NA – Not Applicable		NI – Not Inspected		
Water Use			Condition		Comment		Site Conditions			Condition		Comment	
Intake/Screen			NA				Water Management Structures			A			
Flow Measure. Device			NA				Culverts / Bridges			NA			
Source:			NA				Drainage			NA			
Water Use:			NA				Erosion / Sediment			NA			
Recirculation (y /n)			NA				Mitigation Measures			NA			
							Reclamation Activities			NA			
							Materials Storage			NA			
Waste Disposal							Signage			NA			
Waste Water			NA										
Solid Waste			NA				Monitoring						
Hazardous Waste			NA				Sample Collection / Analysis			NA			
SECTION 1			<input checked="" type="checkbox"/> Comments		<input type="checkbox"/> Non-Compliance with Act or Licence		<input type="checkbox"/> Action Required						
Background													
The Chesterfield Inlet Landfarm was developed in 2013 to hold and remediate approximately 150m ³ of hydrocarbon-contaminated soils.													
Inspectors Statement													
This inspection, conducted on July 7, 2014, is the first inspection of this facility by Aboriginal Affairs and Northern Development Canada and focused on determining compliance with the water license.													
Observations on Site													
1. At the time of inspection and through correspondence with the licensee it was determined that no water had been used or will be used, and it was determined that no waste had been deposited to water, or will be deposited to water through this activity.													
2. The berms surrounding the land farm appeared to be in good condition. There were some sections where the top layer of gravel was washed out and the geo-textile lining was showing. Please continue to monitor.													
SECTION 2			<input checked="" type="checkbox"/> Comments		<input type="checkbox"/> Non-Compliance with Act or Licence		<input type="checkbox"/> Action Required						
Given that the current landfarm does not deposit waste into water and does not use water, the Inspector has determined that no water licence or authorization for water use or deposit of waste is required; however, the terms of the current licence remain in effect until cancelled. It is recommended that the licensee contact Government of Nunavut, Department of Environment for further guidance on how to manage contaminated soil.													
Inspector's Name													
Justin Hack													
Signature													
Date													
August 11, 2014													

CC: Robert Eno, Government of Nunavut, Department of Environment
Erik Allain, Manager of Field Operations, Aboriginal Affair and Northern Development Canada
Phyllis Beaulieu, Manager of Licensing, Nunavut Water Board