

NWB Annual Report

Year being reported: 2009 ▼

License No: 1BR-CLI0914 Issued Date: June 17, 2009
 Expiry Date: May 31, 2014

Project Name: PIN-B (Clifton Point) Remediation

Licensee: Indian & Northern Affairs Canada

Mailing Address: Inuksugait Plaza II
 PO Box 2200
 Iqaluit, NU
 X0A 0H0

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

General Background Information on the Project (*optional):

Licence Requirements: the licensee must provide the following information in accordance with

Part B ▼ Item 1 ▼

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	Unnamed Lake (200m south of airstrip)		
Water Quantity:	20 m3/day	Quantity Allowable Domestic (cu.m)	
	2.6 m3/day	Actual Quantity Used Domestic (cu.m)	
	n/a	Quantity Allowable Drilling (cu.m)	
	n/a	Total Quantity Used Drilling (cu.m)	

Waste Management and/or Disposal

- ☒ Solid Waste Disposal
☒ Sewage
☐ Drill Waste
☒ Greywater
☒ Hazardous
☐ Other:

Additional Details:

- All potable water was brought to site.
 - Between August 31, 2009 and September 30, 2010, a total of 31 truck loads, with a capacity of 2,500 L, of non-potable water was hauled to the camp from the unnamed lake (200m south of the airstrip).
 - Sewage generated from the camp was collected from the portable toilets and incinerated daily.
 - Greywater was not discharged from the holding lagoon in 2009.
 - 75 cubic metres of hazardous waste materials were containerized and are being

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)
 Date of Spill:
 Date of Notification to an Inspector:
 Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

Revisions to the Spill Contingency Plan

SCP addendum attached for Board consideration ▼

Additional Details:

As requested, a revised Spill Contingency Plan is attached for consideration.

Revisions to the Abandonment and Restoration Plan

Other: (see additional details) ▼

Additional Details:

Revised Remedial Action Plan, dated November 9 2009 forwarded for consideration.

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

Work complete in 2009:

- Mobilization (complete)
- Camp setup (complete)
- Hazardous material removal & containerization (40% complete)
- Building demolition (40% complete)
- Non-Hazardous landfill construction (complete)
- Placement of debris into landfill (30% complete)

Work planned for 2010:

- Tier II soil excavation, containerization and offsite disposal
- Hazardous material removal, containerization and offsite disposal (continued)
- Building demolition (continued)
- Excavation and treatment of hydrocarbon contaminated soil
- Buried debris excavation
- Surface debris collection and disposal
- Placement of debris in landfill (continued)
- Demobilization

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Details described below



Additional Details:

See "GPS Coodinates" sheet.

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Details described below



Additional Details:

See "GPS Coodinates" sheet.

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board



Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board



Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

No inspection and/or compliance report issued by INAC



Additional Details: (Dates of Report, Follow-up by the Licensee)

Any additional comments or information for the Board to consider

--

Date Submitted:

February 22, 2010

Submitted/Prepared by:

Lou Spagnuolo

Contact Information:**Tel:**

819-997-7247

Fax:

819-934-9229

email:lou.spagnuolo@inac.gc.ca

GPS Coordinates for water sources utilized

[illegible]

GPS Locations of areas of waste disposal

[illegible]