

NWB Annual Report

Year being reported:

Select ▼

2016

License No: 1BR-CLR1419

Issued Date:

May 16, 2014

Expiry Date:

May 15, 2019

Project Name:

Remediation of Contwoyto Lake former Weather Station

Licensee:

Aboriginal Affairs and Northern Development Canada (AAANDC),
now referred to as Indigenous and Northern Affairs Canada (INAC)

Mailing Address:

PO Box 2200
Iqaluit, NU
X0A 0H0Name of Company filing Annual Report (if different from Name of Licensee please clarify
relationship between the two entities, if applicable):

General Background Information on the Project (*optional):

Contwoyto Lake weather station was in operation from the ~1950s until 1982. A Phase III ESA and RAP were completed in 2013. The remedial work began in 2014. Demobilization occurred in 2015. No further work is scheduled at the site. The application for the water license was to conduct remedial works.

Licence Requirements: the licensee must provide the following information in accordance with

Part B ▼

Item 1 ▼

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):

Contwoyto Lake

Water Quantity:

0

Quantity Allowable Domestic (cu.m)

0

Actual Quantity Used Domestic (cu.m)

Not Applicable

Quantity Allowable Drilling (cu.m)

Not Applicable

Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

- ☐ Solid Waste Disposal
☐ Sewage
☐ Drill Waste
☐ Greywater
☐ Hazardous
☐ Other:

Additional Details:

No work or monitoring activities took place in 2016.

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)
 Date of Spill:
 Date of Notification to an Inspector:
 Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

No work or monitoring activities took place in 2016.

Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed

Additional Details:

No work or monitoring activities took place in 2016.

Revisions to the Abandonment and Restoration Plan

AR plan submitted and approved - no revision required or proposed

Additional Details:

No work or monitoring activities took place in 2016.

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

No work or monitoring activities took place in 2016.

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Not Applicable (N/A)

Additional Details:

No work or monitoring activities took place in 2016.

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Not Applicable (N/A)

Additional Details:

No work or monitoring activities took place in 2016.

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board

Additional Details: (date of request, analysis of results, data attached, etc)

No work or monitoring activities took place in 2016.

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board

Additional Details: (Attached or provided below)

No work or monitoring activities took place in 2016.

Any responses or follow-up actions on inspection/compliance reports

Select


Additional Details: (Dates of Report, Follow-up by the Licensee)

No work or monitoring activities took place in 2016.

Any additional comments or information for the Board to consider

There was insufficient volumes of water within the monitoring wells to obtain samples and the monitoring wells were decommissioned during final demobilization in March 2015. Confirmatory sampling was completed and the details are included in the Final Remediation Report for Contwoyto. Specific references to the Confirmatory Treatment area sampling is found between pg 29-31 in part 1 of the attached remediation report. This includes post construction sampling, which references summary tables C-2 & C-3 that are found in part 3 of the attached remediation report .

Date Submitted:	March 8, 2017
Submitted/Prepared by:	Erika Solski
Contact Information:	Tel: 867-975-4577
	Fax: 867-975-4736
	email: Erika.Solski@aandc.gc.ca



]