



NWB Tools

Phyllis Beaulieu <phyllis.beaulieu@nwb-oen.ca>

Fwd: Response to Contwoyto Water Licence # 1BR-CLR1419 Inspection by Eva Paul July 16 2014

Robin Ikkutisluk <robin.ikkutisluk@nwb-oen.ca>

Wed, Nov 26, 2014 at 11:25 PM

To: "Phyllis Beaulieu (licensing@nunavutwaterboard.org)" <phyllis.beaulieu@nwb-oen.ca>

----- Forwarded message -----

From: **Erika Solski** <Erika.Solski@aandc-aadnc.gc.ca>

Date: Mon, Nov 3, 2014 at 8:43 AM

Subject: Response to Contwoyto Water Licence # 1BR-CLR1419 Inspection by Eva Paul July 16 2014

To: Baba Pedersen <Baba.Pedersen@aandc-aadnc.gc.ca>, Erik Allain <Erik.Allain@aandc-aadnc.gc.ca>, licensing@nunavutwaterboard.org, cory.zyla@nwb-oen.ca, robin.ikkutisluk@nwb-oen.ca

Cc: Eva Paul <Eva.Paul@aandc-aadnc.gc.ca>, Mark Yetman <Mark.Yetman@aandc-aadnc.gc.ca>

Hi All,

Please find below some updates to the Contwoyto Lake Remediation Project that were brought to our attention by a water licence inspection by Eva Paul on July 16, 2014.

In section 3 of the inspection report, there are 5 actions required. Please see below responses.

1) GPS Coordinates of the monitoring wells that were installed after the site inspection on July 16, 2014.

M1 65 29' 5.96" N	M2 65 29' 5.17"N	M3 65 29'
3.84"N	M4 65 29' 2.4"N	
-110 22' 19.34"W	-110 22' 12.29"W	-110
22' 5.3"W	-110 22' 5.3"W	

2) GPS Coordinates for the borrow area that was submitted under our Quarry Permit Application to AANDC Lands. Please see below Borrow Coordinates.

B1 65 29' 6.96154" N	B2 65 29' 5.902941" N	B3 65 29'
1.4603" N	B4 65 29' 0.094779" N	
-110 22' 22.2475" W	-110 22' 24.02241" W	-110 22'
0.414113" W	-110 22' 2.157712" W	

3) Contact water is to be collected tested and treated as required as per licence conditions. Please see attached memo on contact water at Contwoyto Lake.

4) Please find attached stamped engineered drawings of the Landfarm design (Proposed in June 2014 and as built in July 2014).

5) Some slight changes to Part D 8. & 9. of the current water licence. All site greywater and sewage generated from camp operations were being contained and shipped off-site. These changes would have less impacts than what was originally proposed and actually exceeds the current water licence requirements.

This should address all of Section 3 of the Water Licence Inspection document from July 16, 2014. Please let me know if you require anything further.

If you have any questions or concerns please do not hesitate to contact

me.

Thanks,

Erika Solski
Project Manager, Lands and Contaminated Sites Directorate
Aboriginal Affairs and Northern Development Canada (AANDC)/
Affaires autochtones et Développement du Nord Canada (AADNC)
Nunavut Region / Région du Nunavut
P.O. Box 2200
Qimuguil Bldg. 2nd Floor
Iqaluit, NU X0A 0H0
Phone / Téléphone: (867) 975-4577
Fax / Télécopieur: (867) 975-4736
Email / Courriel: Erika.Solski@aandc-aadnc.gc.ca

3 attachments



**IQALUIT-#859560-v1-
CONTWOYTO_DELTA_PROPOSED_SOIL_TREATMENT_AREA_CELL_JUNE_2014_DRAWING.PDF**
533K



**IQALUIT-#859561-v1-
CONTWOYTO_DELTA_SOIL_TREATMENT_AREA_CELL_ASBUILT_JULY_2014_DRAWING.PDF**
533K



**IQALUIT-#868173-v1-
Contwoyto_contact_water_memo_from_Delta___Carter_in_response_to_water_licence_inspection_july_2014.PDF**
208K