



WATER USE INSPECTION REPORT

Date: August 9, 2011	Licensee Rep. (Name/Title): No Representative
Licensee: Barrick Gold Inc. (Barrick)	Licence No.: 1BR-CUL1118

The Cullaton Lake project is in the monitoring stage and the current licence allows for the monitoring of waste only. No water use is authorized and very few structures remain.

WATER SUPPLY

Source(s): No Water Use Authorized	Quantity Permitted: NA
Owner:/Operator: Barrick	

Indicate: **A** - Acceptable **U** - Unacceptable **NA** - Not Applicable **NI** - Not Inspected

Intake Facilities: NA	Storage Structure: NA	Treatment Systems: NA	Chemical Storage: NA
Flow Meas. Device: NA	Conveyance Lines: NA	Pumping Stations: NA	Screen : NA

Comments: No water use is authorized at this site and no activities are occurring at this time.

WASTE DISPOSAL

Sewage: Sewage Treatment System (Prim./Sec/Ter.): NA

Natural Water Body: NA	Continuous Discharge (land or water): NA	
Seasonal Discharge: NA	Wetlands Treatment: NA	Trench: NA

Indicate: **A** - Acceptable **U** - Unacceptable **NA** - Not Applicable **NI** - Not Inspected

Discharge Quality: NA	Decant Structure: NA	Erosion: NA
Discharge Meas. Device: NA	Dyke Inspection: NA	Seepages: NA
Dams, Dykes: NA	Freeboard: NA	Spills: NA
Construction: NA	O&M Plan: NA	A&R Plan: NI
Discharge: NA	Effluent Discharge Rate: NA	

Comments: Site is inactive and no wastes are being produced.

Solid Waste:

Owner/Operator:

Landfill: NA	Burn & Landfill: NA	Other: NA
--------------	---------------------	-----------

Comments: NA

FUEL STORAGE:

Waste Oil Storage:

Owner/Operator:

Indicate: **A** - Acceptable **U** - Unacceptable **NA** - Not Applicable **NI** - Not Inspected

Berms & Liners: U	Water within Berms: U	Evidence of Leaks: NI
Drainage Pipes: NI	Pump Station & Catchments Berm: NA	
Pipeline Condition: NA	Condition of Tanks: A	

Comments: There are numerous drums of fuel stored near the airstrip with no secondary containment with the exception of a few. The drums belong to various companies that use the airstrip.

SURVEILLANCE NETWORK PROGRAM (SNP)

Samples Collected		Owner /Operator:	
3		INAC:.Tailings outfall, Shear Creek & pool at Toe of quartzite pile	
Signs Posted	SNP:		Warning:
Records & Reporting:			
Geotechnical Inspection:			

Non-Compliance of Act or Licence:

- Fuel near airstrip should be stored in secondary containment.

Ian Rumbolt

Inspector's Name

Sent by E-mail

Inspector's Signature