## Barrick Gold Inc.

Field Office: 1084 County Rd 8 Campbellford, ON K0L 1L0 T: (705) 632-1871 F: (705) 632-0755 E: pbrugger@barrick.com

February 15, 2016

Ms. Stephanie Autut Executive Director, Nunavut Water Board P. O. Box 119 Gjoa Haven, Nunavut X0B 1J0 Nunavut Water
Board
FEB 2 5 2016\*
Public Registry

Dear Ms. Autut:

Pursuant to Part D, Article 8(d) and (e) of Water Licence 1BR-CUL1118, please find appended 2 paper copies of a report by exp Inc. entitled "2015 Tailings Dam Examination, Cullaton Lake Gold Mine". A third electronic copy has been e-mailed to you concurrent with this release.

Summarized, the consultant recommends continued annual visual surveillance of the Tailings Pond No. 1 spillway for erosion and Station 940-20 for artesian conditions. As in the past these will be addressed during the annual site visit.

I apologize for the tardiness of this report. As you may know we are also currently completing a Dam Safety Review and some reference and review was required by our consultants. The Dam Safety Review will be released shortly.

Sincerely,

Paul Brugger

Site Manager, Cullaton Lake

Attachments: As Stated

Cc Jim Alto, Director: Environment, Capital Projects and Mine Closure
Ian Parsons, Water Resources Coordinator, Indian and Northern Affairs Canada