



March 11, 2016

Manager of Licensing Nunavut Water Board PO Box 119 Gjoa Haven, Nunavut XOB 1J0



RE: 1BR-DYE0914 2014 Annual Report Deficiencies Monitoring Reports

Please find enclosed the DYE-M, Cape Dyer Baseline and First Year Environmental Monitoring Report — Environmental Sciences Group and the DYE-M, Cape Dyer Year 1 Landfill Monitoring Report — AECOM. They are being submitted by Defence Construction Canada on behalf of the Department of National Defence. We trust that these reports address the deficiencies outlined by the Nunavut Water Board in the letter dated 3 March 2016 and fulfill the obligations to provide a 2014 Annual Report under licence 1BR-DYE0914 pursuant to Section 14.1 of the Nunavut Water Regulations (SOR/2013-69).

Should you have any questions regarding this information please do not hesitate to contact me at (613) 995-9741

Thank you,

Tamara Van Dyck BSc Coordinator, Environmental Services Defence Construction Canada

613-995-9741

Tamara.VanDvck@dcc-cdc.qc.ca

Enclosure: CD DYE-M, Cape Dyer Baseline and First Year Environmental Monitoring Report – Environmental Sciences Group DYE-M, Cape Dyer Year 1 Landfill Monitoring Report – AECOM

