

NWB Annual Report

Year being reported: 2012



License No: 1BR-EKA1017

Issued Date: March 1, 2012

Expiry Date: September 30, 2017

Project Name: FOX-C Ekalugad Fjord Remediation Project

Licensee: Aboriginal Affairs and Northern Development Canada (AANDC)

Mailing Address: PO Box 2200
Iqaluit NU
X0A 0H0

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

N/A

General Background Information on the Project (*optional):

The FOX-C Intermediate Distant Early Warning (DEW) Line Site was constructed in 1957 and subsequently abandoned in 1963. It is located on the Northeast coast of Baffin Island, Nunavut on the south shore of Ekalugad Fjord. It is approximately 240 kilometres northwest of Qikiqtarjuaq and 260 kilometres south of Clyde River.

The remediation phase of the FOX-C Ekalugad Fjord Remediation Project was completed over 3 field seasons (2006-2008). The first three years of the 25-year long-term monitoring at FOX-C were completed in August 2009, and July 2011 with no monitoring completed in 2010.

No monitoring activities occurred in 2012.

License Requirements: the licensee must provide the following information in accordance with

Part B



Item 1



A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s): Monitoring Wells at Non-Hazardous Landfill (See GPS Coordinates Page)

Water Quantity:	N/A	Quantity Allowable Domestic (cu.m)
	N/A	Actual Quantity Used Domestic (cu.m)
	N/A	Quantity Allowable Drilling (cu.m)
	N/A	Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

☐ Solid Waste Disposal

- ☐ Solid Waste Disposal
- ☐ Sewage
- ☐ Drill Waste
- ☐ Greywater
- ☐ Hazardous
- ☐ Other:

Additional Details:

No long term monitoring took place at FOX-C in 2012 so no waste was generated.

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed



Additional Details:

Revisions to the Abandonment and Restoration Plan

AR plan submitted and approved - no revision required or proposed



Additional Details:

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

WORK COMPLETED

- Visual monitoring of the NHWL
- Natural environment monitoring the site
- The five monitoring wells on site could not be sampled as they were frozen

FUTURE WORK PROPOSED

- Continue the 25 year Long-Term Monitoring Plan
- Future events if warranted, will occur in 2013, 2015, 2018, 2023 and 2033.

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Details attached



Additional Details:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Details attached



Additional Details:

No long term monitoring took place at FOX-C in 2012.

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board



Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board



Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

No inspection and/or compliance report issued by INAC



Additional Details: (Dates of Report, Follow-up by the Licensee)

Any additional comments or information for the Board to consider

The site was not visited in 2012 so AANDC has nothing to report regarding site activities for 2010. The next long term monitoring event is scheduled to take place 2013.

Date Submitted:	July 28, 2014
Submitted/Prepared by:	Natalie Plato
Contact Information:	Tel: 867-975-4730
	Fax: 867-975-4560
	email: natalie.plato@aandc.gc.ca

GPS Coordinates for water sources utilized

Source Description	Latitude			Longitude		
	Deg °	Min ,	Sec "	Deg °	Min ,	Sec "
Non-Hazardous						
MW South	68	43	47	-68	39	12.76
MW East	68	43	50	-68	39	7.523
MW North	68	43	51	-68	39	15.45
MW	68	43	49	-68	39	17.39
MW	68	43	48	-68	39	16.36