

Visual Inspection Checklist
Inspection Report • Page 1 of 2

SITE NAME - HELIPAD
LANDFILL / AREA DESIGNATION - Landfill, upper site, West of SRR
DATE OF INSPECTION - Aug 25-28, 2005
DATE OF PREVIOUS INSPECTION - July 2003
INSPECTED BY: Dominic Laforge, Adamie Onalik
REPORT PREPARED BY: Anne Marie Laroche, Tiivi Qiatsuk, Simon Desjardins
The preparer represents to the best of the preparer's knowledge, the following statements and observations are true and correct and to the best of the preparer's actual knowledge, no material facts have been suppressed or misstated.