Inspection Report (Barrel dump) • Page 2 of 2

Checklist Item	Present Yes / No	Location (Describe relative to existing monuments / features and relative to landfill / area design i.e. surface, berms, toe)	Length	Width	Depth	Extent relative to area extent of Landfill Area (%)	Description	Photographic Records Focal Length Location, view point & direction Feature of note Scale	Additional Comments Preliminary Stability Assessment
Settlement	No						No settlement or stain or erosion observed at the barrel dump	No. 2-5, scale on photo	No sign of settlement, erosion or stain in the drainage path of the barrel dump
Erosion	No								
Frost action	No								
Animal Burrows	No								
Vegetation	No	No vegetation observed at upper base							
Staining	No						No sign of staining in the drainage path	No. 2-1, scale on photo	
Vegetation Stress	No								
Seepage Points	No								
Debris Exposed	No								
Presence Condition of Monitoring Instruments	No								
Other features of note		Soil sampling point F4-2 Soil sampling point F4-3 Soil sampling point F4-4 Soil sampling point F4-5 Soil sampling point F4-21 Soil sampling point F4-22 Soil sampling point F4-23 Soil sampling point F4-24					Sample obtained in coarse gravel Sample obtained in gravel Sample obtained in sandy material Sample obtained in gravel Sample obtained in sandy material Sample obtained on steep slope Sample obtained in gravel Sample obtained in sandy material	No. 2-1, facing North, scale on photo No. 2-2, facing east, scale on photo No. 2-3, facing North, scale on photo No. 2-4 facing west, scale on photo No. 2-5, facing West, scale on photo No. 2-6, facing East, scale on photo No. 2-8, facing North, scale on photo No. 2-7, facing West, scale on photo	No observation