

Aug 17/2006

NWS-C is essentially 2 level w
additional gravel piled up along N
from NW corner to SE corner

NWS-C-S 3 shot panoramic R to L
img-0201 trying to show difference in elevation
407887/7597994 looking NE

Moving to West Landfill

NWS-W-1 407882/7598026
sta-0202 Looking N to area of veg and rock
sta-0203 between the landfill areas
sta-0204 - toe of slope indiscernable except for colour

NWS-W-2 407880/7598056 looking N
img-0205 toe barely discernable, no seepage into veg

NWS-U-3st 407854/7598111 looking 130
img-0206 standing on organics looking on to landfill
cap - no sign of seepage, lots of
rotting

Surface is eroding - cannot determine
settlement

Aug 17/2006

NWS-W-4 407856/7598090 looking 225°
- landfill adjacent to much gravel

- colour primary indicator for toe slope
sta-0207 * img-0209 view of cap looking
sta-0208

NWS-W-5 407826/7598065 look S
to SW corner (on organics)
img-0210

NWS-W-6 407880/7598046 looking S
img-0211 - closeup of disturbed veg, no sign seepage

NWS-W-7 407833/7598043 looking E
img-0212 to SE corner toe of organic, no seep

On To The North Landfill 4pm
- There are 3 - biggest is also westerly (W)
middle will be central (C) third is
most easterly (E)

Starting with big one - no settlement or seepage
img-0213 View Dennis K. on the North landfill - landfill
exploring in ATV

North-W-1 408487/7598691 looking 150°
viewed from NW corner

toe barely visible
img-0214

24 60725

Aug 17

North W-2 408493/7598671 V 55°
img-0215 toe on additional rock

North-W-3 408565/7598717 V 320°
Viewed from SE corner - toe on rock

img-0216

North-W-4st 408589/7598719
sta-0217 Viewed from North-C 2 photos
sta-0218

North-W-5 408547/7598739
looking SW along toe
img-0219

North-C-1st 408560/7598734 Looking 115°
sta-0220 two areas of veg adjacent to west toe
sta-0221 no indications of seepage
North-E in distance

North-C-2 408606/7598746 View 200°
img-0222 Looking at North slope (toe into rock)

North-C-3st 2 shots 4086223/7598702
sta-0223 Looking NW from near North-E
sta-0224 * North-W in background

60725

Aug 17²⁵

North-E-1st 408611/7598685 Looking NE
sta-0225
sta-0226

North E-2 408644/7598691 Looking N
img-0227 toe into rocky organic - no seepage

North-E-3 408654/7598718 Looking W
along northern toe North-C in background
img-0228

DONE

Retaking some photos @ MAIN LANDFILL

ML- 407930/7597729 looking 180°
img-0229

ML- 407949/7597618 looking 300°
rotting in foreground right side
img-0230 photo

Inuit hunting crew - bloody shore