

August 29, 2014



Photo #49: Looking east at collected barells and cylinders within the apron LTU.

August 30, 2014



Photo #50: Looking northwest FTA constuction, ballast layer.

August 31, 2014



Photo #51: View looking east FTA LTU construction, ballast layer.

September 1, 2014



Photo #52: View looking east FTA LTU construction, ballast layer.

September 3, 2014



Photo #53: View looking east FTA LTU construction, ballast layer.

September 5, 2014



Photo #54: View looking south, stockpiling ballast material.

September 6, 2014



Photo #55: View looking northwest preparing barrels and cylinders for transportation south.

September 7, 2014



Photo #56: Loading barrels and cylinders.

September 8, 2014



Photo #57: Loading barrels and cylinders for transportation south.

September 10, 2014



Photo #58: Transporting sea cans to the harbour.



Photo #59: View looking northwest, ballast layer leading edge.

September 11, 2014



Photo #60: View looking north, ballast layer.

September 12, 2014



Photo #61: View looking northeast – ballast layer.

September 13, 2014



Photo #62: View looking southwest, stockpiled demarcation material.

September 15, 2014



Photo #63: View looking east, ballast layer.

September 16, 2014



Photo #64: View looking southeast, grading ballast layer.

September 18, 2014



Photo #65: View looking northwest, increasing berm height.



Photo #66: View looking southwest, stockpiling demarcation material.

September 20, 2014



Photo #67: View looking west, preparing demarcation layer.

September 24, 2014



Photo #68: Looking northwest, removing snow in preparation for liner installation.



Photo #69: View looking northwest liner installation.

September 25, 2014



Photo #70: Looking northwest, liner installation.

September 27, 2014



Photo #71: Looking southwest, liner installation.

September 28, 2014



Photo #72: Looking west along southern berm, LTU ramp access.

September 29, 2014



Photo #73: Looking south, loading demarcation material for the FTA LTU.

September 30, 2014



Photo #74: Looking east, spreading demarcation material.

October 1, 2014



Photo #75: Looking northwest, liner installation.

October 2, 2014



Photo #76: Looking east along northern berm, liner installation.

October 3, 2014



Photo #77: Looking north east toward south east corner of FTA LTU.

October 4, 2014



Photo #78: Looking east, uncovered liner to be address in 2015.