

EXECUTIVE SUMMARY
2020/2021 Annual Report for TC Licence No. 1BR-FTA1828
Cambridge Bay Land Treatment Units

Transport Canada has two land treatment units located at the Cambridge Bay Airport in Nunavut. The land treatment units were built to contain and treat contaminated soil from two different locations on the airport property. It was not possible for Transport Canada to conduct any on-site environmental monitoring in 2020 due to Covid-19 travel restrictions. Transport Canada organized site inspection and water pumping activities at the two land treatment units on August 6th and 7th, 2020. This work was completed by a local company and did not require personnel to travel into Cambridge Bay.

Transport Canada will continue annual monitoring and maintenance at the land treatment units in accordance with its NWB Licence and will update the NWB on its future plans for operation and eventual site closure.