

Table A-1. CAM-2 Gladman Point, Summary of 2008 Soil Analysis - Station Area Landfill

Sample Ident.	Sample Location			Depth	Copper Cu	Nickel Ni	Cobalt Co	Cadmium Cd	Lead Pb	Zinc Zn	Chromium Cr	Arsenic As	Mercury Hg	PCB Total Aroclors	F1 C6-C10	F2 C10-C16	F3 C16-C34	TPH C6-34
	Location Id.	Northing	Easting		(m)	(mg/kg)	(mg/kg)	(mg/kg)	(mg/kg)	(mg/kg)	(mg/kg)	(mg/kg)	(mg/kg)	(mg/kg)	(mg/kg)	(mg/kg)	(mg/kg)	(mg/kg)
Upgradient Samples																		
C2-5A	C2-5	7619020	548349	0.1	3.7	<5.0	<2.0	<0.50	2.5	3.8	2.3	<5.0	<0.050	<0.050	<10	<30	<50	ND
C2-5B	C2-5	7619020	548349	0.5	4.8	<5.0	<2.0	<0.50	6.1	6.8	5.9	<5.0	<0.050	<0.050	<10	<30	<50	ND
Downgradient Samples																		
C2-1A	C2-1	7619113	548458	0.1	4.2	<5.0	<2.0	<0.50	4.4	6.9	5.9	<5.0	<0.050	<0.050	<10	<30	<50	ND
C2-1B	C2-1	7619113	548458	0.2	4.1	<5.0	<2.0	<0.50	4.7	6.6	6.2	<5.0	<0.050	<0.050	<10	<30	<50	ND
C2-16A *	C2-1	7619113	548458	0.1	3.3	<5.0	<2.0	<0.50	4.2	5.9	5.3	<5.0	<0.050	<0.050	<10	<30	<50	ND
C2-2A	C2-2	7619084	548487	0.1	11.6	6.1	2.3	<0.50	4.5	9.1	6.7	<5.0	<0.050	<0.070	<10	<30	136	136
C2-2B	C2-2	7619084	548487	0.2	2.5	<5.0	<2.0	<0.50	<2.0	3	2.3	<5.0	<0.050	<0.050	<10	<30	<50	ND
C2-3A	C2-3	7619002	548533	0.1	1.2	<5.0	<2.0	<0.50	2.2	3.1	2.9	<5.0	<0.050	<0.050	<10	<30	<50	ND
C2-3B	C2-3	7619002	548533	0.4	1.8	<5.0	<2.0	<0.50	2.4	3	2.5	<5.0	<0.050	<0.050	<10	<30	<50	ND
C2-4A	C2-4	7618948	548579	0.1	1.1	<5.0	<2.0	<0.50	<2.0	3.8	2.9	<5.0	<0.050	<0.050	<10	<30	<50	ND
C2-4B	C2-4	7618948	548579	0.2	1.9	<5.0	<2.0	<0.50	2.3	3.7	3.6	<5.0	<0.050	<0.050	<10	<30	<50	ND

* Denotes duplicate sample. (Further information located in Table 2 of main report)

Note: mg/kg = ug/g

TPH = The sum of F1, F2, and F3 as per the TOR

ND = No detectable concentrations observed