

Visual Inspection Checklist
Inspection Report – Page 1 of 3

SITE NAME:	CAM-2 Gladman Point
LANDFILL/AREA DESIGNATION:	West Landfill - North and South
DATE OF INSPECTION:	August 19, 2008
DATE OF PREVIOUS INSPECTION:	August 26, 2007
INSPECTED BY:	Jim Theriault
REPORT PREPARED BY:	Jim Theriault

The preparer represents to the best of the preparer's knowledge, the following statements and correct and to the best of the preparer's actual knowledge, no material facts have been suppressed

Preliminary Stability Assessment

Feature	Severity Rating	Extent
Settlement	Not Observable	None
Erosion	Not Observable	None
Frost Action	Not Observable	None
Animal Burrows	Not Observable	None
Vegetation	Not Observable	None
Staining	Not Observable	None
Vegetation Stress	Not Observable	None
Seepage Points	Not Observable	None
Debris Exposed	Not Observable	None
Tension Crack	Not Observable	None
Overall Landfill Performance	Acceptable	

Inspection Report - Page 2 of 3

Checklist Item	Present Yes/No	Location	Dimensions (m)			Extent (% Landfill Surface)	Description	Photographic Records (Photos referenced in photolog and in figures)	Additional Comments/ Preliminary Stability Assessment
			Length	Width	Depth				
Settlement	No	N/A	N/A	N/A	N/A	None	N/A	N/A	N/A
Erosion	No	N/A	N/A	N/A	N/A	None	N/A	N/A	N/A
Frost Action	No	N/A	N/A	N/A	N/A	None	N/A	N/A	N/A
Animal Burrows	No	N/A	N/A	N/A	N/A	None	N/A	N/A	N/A
Vegetation	No	N/A	N/A	N/A	N/A	None	N/A	N/A	N/A
Staining	No	N/A	N/A	N/A	N/A	None	N/A	N/A	N/A
Vegetation Stress	No	N/A	N/A	N/A	N/A	None	N/A	N/A	N/A
Seepage Points	No	N/A	N/A	N/A	N/A	None	N/A	N/A	N/A
Debris Exposed	No	N/A	N/A	N/A	N/A	None	N/A	N/A	N/A
Presence/ Condition of Monitoring Instruments	No	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Other Features of Note.	No	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A
Additional Photos	Yes	Refer to Figures B-1 and B-2	N/A	N/A	N/A	N/A	Inspection photos	Photos WLFN 1 thru 16 and WLFS 1 thru 14	General photos for documentation, no features of note

Inspection Report - Page 3 of 3

Performance/Severity Rating	Description
Acceptable	Noted features are of little consequence. The landfill is performing as designed. Minor deviations in environmental or physical performance may be observed, such as isolated areas of erosion, settlement.
Marginal	Physical/environmental performance appears to be deteriorating with time. Observations may include an increase in size or number of features of note, such as differential settlement, erosion or cracking. No significant impact on landfill stability to date, but potential for failure is assessed as low or moderate.
Significant	Significant or potentially significant changes affecting landfill stability, such as significant changes in slope geometry, significant erosion or differential settlement; scarp development. The potential for failure is assessed as imminent.
Unacceptable	Stability of landfill is compromised to the extent that ability to contain waste materials is compromised. Examples may include: <ul style="list-style-type: none"> - Debris exposed in erosion channels or areas of differential settlement. - Liner exposed. - Slope failure.

Extent	Description
Isolated	Singular feature
Occasional	Features of note occurring at irregular intervals/locations
Numerous	Many features of note, impacted less than 50% of the surface area of the landfill
Extensive	Impacting greater than 50% of the surface area of the landfill