



NWB Tools

Ida Porter <ida.porter@nwb-oen.ca>

1BR-HLR1314 Cancellation

Brady MacCarl <brady.maccarl@nwb-oen.ca>

Wed, Aug 26, 2015 at 10:37 AM

To: Ida Porter <ida.porter@nwb-oen.ca>, Licensing Department <licensing@nwb-oen.ca>

Cc: Karén Kharatyan <karen.kharatyan@nwb-oen.ca>

Hi Ida,

Please review information and forward it to the Licensee.

Regarding Licence Number 1BR-HLR1314, the Licensee has not submitted an Application to cancel the Licence, and although the Inspector's report indicates the remediation requirements have been met, the Hope Lake Licence indicates the possibility of long-term monitoring at the site and the Licensee did not indicate in the 2013 or 2014 Annual Reports whether this activity is being pursued. Please advise the Licensee that it should submit an application to cancel the Licence if no other activities are planned under the Licence.

Also, the Licence contains the following outstanding conditions that must be addressed either before or in tandem with any potential cancellation application:

Pursuant to **Part D, Item 16**, contaminated soils were to be disposed of off-site, yet the 2013 Annual Report indicates that PHC contaminated soil was treated in an on-site treatment facility.

Pursuant to Part E, Items 2 and 3, The Licensee was to submit to the Board for approval, within sixty (60) days prior to commissioning, an Operation and Maintenance Manual for all facilities constructed under the Hope Lake Remediation Project, including the Sewage Treatment Facility. The NWB has no record of receiving this Plan.

Pursuant to **Part H, Item 1**, the Licensee was to submit to the Board for review within sixty (60) days prior to the construction of the Sewage Treatment Facility, complete for-construction engineering design drawings, signed and stamped by an Engineer. The NWB has no record of receiving these drawings.

Pursuant to **Part H, Item 2**, The Licensee was to provide to the Board, within ninety (90) days of completion of construction, as-built plans and drawings of Sewage Treatment Facility. The NWB has no record of receiving these drawings.

Pursuant to **Part K, Item 1**, The Licensee was to submit to the Board for review, within sixty (60) days subsequent to completion of remediation activities, a Post Remediation Report that includes analytical results obtained from sampling conducted to determine whether remediation objectives have been satisfied. The NWB has no record of receiving this Report.

Pursuant to **Part K, Item 3**, the Licensee was to submit a Post-closure Monitoring Plan if further monitoring activities were planned. The NWB has not received indication of whether further monitoring activities are planned at the Hope Lake site.

2/2