

NWB Annual Report

Year being reported: 2020

License No: 2BE-GRE1621

Issued Date: October 6, 2016

Expiry Date: October 5, 2021

Project Name:

Greyhound Exploration Project

Licensee:

Aura Silver Resources Inc.

Mailing Address:

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

Agnico Eagle Mines Ltd.

General Background Information on the Project (*optional):

Aura Silver Resources Inc. and Agnico Eagle Mines Ltd. entered into and Option Agreement on June 1st, 2014. Agnico Eagle is the operator of the project and is responsible for all permits.

Licence Requirements: the licensee must provide the following information in accordance with

Part B

Item 2

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	Local lakes and ponds		
Water Quantity:	0	Quantity Allowable Domestic (cu.m)	
	0	Actual Quantity Used Domestic (cu.m)	
	100m³/day	Quantity Allowable Drilling (cu.m)	
	0	Total Quantity Used Drilling (cu.m)	

Waste Management and/or Disposal

☐ Solid Waste Disposal

☐ Sewage

☐ Drill Waste

☐ Greywater

☐ Hazardous

☐ Other:

Additional Details:

No drilling activities were conducted in 2020.

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.: (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

No unauthorized discharge in 2020.

Revisions to the Spill Contingency Plan

SCP submitted and approved - no revision required or proposed

Additional Details:

Revisions to the Abandonment and Restoration Plan

AR plan submitted and approved - no revision required or proposed

Additional Details:

Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

No reclamation conducted in 2020 except some cleanup at drilling sites GHD19-31 and GHD19-32 as it was requested by the inspector.

Results of the Monitoring Program including:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;

Not Applicable (N/A)

Additional Details:

The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;

Not Applicable (N/A)

Additional Details:

Results of any additional sampling and/or analysis that was requested by an Inspector

No additional sampling requested by an Inspector or the Board

Additional Details: (date of request, analysis of results, data attached, etc)

Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.

No additional sampling requested by an Inspector or the Board

Additional Details: (Attached or provided below)

Any responses or follow-up actions on inspection/compliance reports

Inspection and Compliance Report received by the Licensee (Date):

Additional Details: (Dates of Report, Follow-up by the Licensee)

CIRNAC inspection report dated September 12th, 2019. Small amount of garbage/debris was noted by the inspector in August 1st, 2019 at drilling sites. Cleanup was completed in September 2020 at drilling sites GHD19-31 and GHD19-32 and this information was submitted to the inspector as required.

Any additional comments or information for the Board to consider

Date Submitted:
Submitted/Prepared by:
Contact Information:

March 31, 2021	
David Frenette, Environmental Coordinator	
Tel:	819-874-5980 ext. 4103622
Fax:	
email:	david.frenette@agnicoeagle.com