



## Inspection Report

**License #:** 1BR-LON

**Inspector:** A.Keim

**CIDMS #** 388836

Client	Defence Construction Canada		
Mailing Address	Constitution Square, Suite 1720, 350 Albert St., Ottawa, Ontario K1A 0K3		
Inspection site location	Baffin Region		
Contact name	Douglas Craig	Title	Environmental Officer
Last inspection date			
Inspection start date	July 18, 2009		
Region	Qikiqtani		



INAC, Nunavut District  
P.O. Box 100  
Building 918  
Iqaluit, NU, X0A 0H0

Submitted Via E-Mail  
Our File: 1BR-LON 0813  
Your File: \_\_\_\_\_  
CIDM # 388836

February 3, 2010

Douglas Craig, M.Sc.  
Environmental Officer  
DEW Line Clean Up  
Defence Construction Canada  
Constitution Square, Suite 1720, 350 Albert St.,  
Ottawa, Ontario  
K1A 0K3

**RE: Water license Inspection – Longstaff Bluff Clean Up – July 18, 2009**

The following inspection report is generated on the information collected during a compliance inspection carried out on the Longstaff Bluff – Fox-2 Clean-up Project and facilities. The inspection was conducted to determine compliance with the terms and conditions of the Water License (1BR-LON0813) issued to Defence Construction Canada (DCC) by the Nunavut Water Board (NWB).

The report references the applicable parts of the Water License (1BR-LON0813) and the findings observed under each of those parts. During the writing of this report a compliance review was undertaken of the documents, plans and manuals filed by the Licensee and located on the Nunavut Water Board's FTP site.

The Inspector thanks Mr. Douglas Craig and Mr John Vanhoof both of DCC for their assistance, time and advice during the inspection. A review of the terms and conditions of the water license was completed with both parties following the individual inspections.

**Issues noted in previous Inspections;**

- None – First inspection of site

**During the period of the 2009 inspection the following issues were identified by the Inspector;**

- o No significant compliance issues were noted during the Inspection. Camp was recently opened and work had recently begun on the project.

**Non-Compliance:** Issues identified during the inspection and/or review of relevant material

**Issues with a known or anticipated human health impacts;**

None

**Issues where there is a known or anticipated environmental impairment;**

None

**Issues where there is a known or suspected violation of a requirement of the Water License or Act;**

None



Indian and Northern  
Affairs Canada

Affaires indiennes  
et du Nord Canada

**Andrew Keim**  
Inspector's Name

\_\_\_\_\_  
Inspector's Signature

Cc:

Peter Kusugak - Manager Field Operations Section- Indian and Northern Affairs Canada

Phyllis Beaulieu – Manager licensing – Nunavut Water Board







Date	Flow	Volume
June 27	2.20	4.20
June 28	2.20	4.20
June 29	2.20	4.20
June 30	1.10	2.20
July 1	1.10	2.20
July 2	2.20	4.20
July 3	2.20	4.20
July 4	2.20	4.20
July 5	2.20	4.20
July 6	2.20	4.20
July 7	2.20	4.20
July 8	2.20	4.20
July 9	2.20	4.20
July 10	2.20	4.20
July 11	2.20	4.20
July 12	2.20	4.20
July 13	2.20	4.20
July 14	2.20	4.20



























