



May 6, 2014

Phyllis Beaulieu Manager of Licensing Nunavut Water Board PO Box 119 Gjoa Haven, Nunavut



RE: Long Term Monitoring Reports for DEW Line sites

Dear Phyllis:

As you are aware most of the DEW Line sites are now in the long term monitoring phase of remediation. The current agreement between DND and NTI has the monitoring structured to include; Phase I (years 1-5 post construction), Phase II (years 7, 10, 15, and 25) and Phase III (yet to be determined). I have enclosed the reports generated by the monitoring contractors for the 2013 field season. Below is a summary of what occurred at each of the sites; please notice for those sites where no activity occurred in 2013, no annual report will be submitted to the NWB.

Site	Activity	Reporting
PIN-2	Year 2 – Monitoring Program (Phase I)	Monitoring report enclosed
PIN-3	No activity on this site 2013	No report to submit
PIN-4	Year 1 – Monitoring Program (Phase I)	Monitoring report enclosed
CAM-M	No activity on this site 2013	No report to submit
CAM-1	Year 4 - Monitoring Program (Phase I)	Monitoring report enclosed
CAM-2	No activity on this site 2013	No report to submit
CAM-3	No activity on this site 2013	No report to submit
CAM-4	Year 7 - Monitoring Program (Phase II)	Monitoring report enclosed
CAM-5	Year 3 - Monitoring Program (Phase I)	Monitoring report enclosed
FOX-M	No activity on this site 2013	No report to submit
FOX-2	Year 2 - Monitoring Program (Phase I)	Monitoring report enclosed
FOX-3	Year 2 - Monitoring Program (Phase I)	Monitoring report enclosed
FOX-4	Construction	NWB Annual Report Submitted March 27, 2014
FOX-5	No activity on this site 2013	No report to submit
DYE-M	Construction	NWB Annual Report Submitted February 26, 2014

Should you have any questions regarding this information please do not hesitate to contact me at (613) 995-9741

Thank you,

Tamara Van Dyck BSc

Coordinator, Environmental Services

Defence Construction Canada

613-995-9741

Tamara.VanDyck@dcc-cdc.qc.ca

