

NWB Annual Report

Year being reported:

Select ▼

2017

License No: 1BR-MDR1721

Issued Date: July 31, 2017

Expiry Date: July 30, 2021

Project Name: Former Iqaluit Metal Dump Remediation Project

Licensee: Transport Canada

Mailing Address: 344 Edmonton Street  
Winnipeg, Manitoba  
R3B 2L4

Name of Company filing Annual Report (if different from Name of Licensee please clarify relationship between the two entities, if applicable):

General Background Information on the Project (\*optional):

Transport Canada applied to the NWB for a Water Licence to allow for the use of Water and deposit of Waste during remediation of the Former Iqaluit Metal Dump.

Licence Requirements: the licensee must provide the following information in accordance with

Part B ▼ Item 1 ▼

A summary report of water use and waste disposal activities, including, but not limited to: methods of obtaining water; sewage and greywater management; drill waste management; solid and hazardous waste management.

Water Source(s):	stream and pond water	
Water Quantity:	50 m3 per day	Quantity Allowable Domestic (cu.m)
	100 m3 total	Actual Quantity Used Domestic (cu.m)
		Quantity Allowable Drilling (cu.m)
		Total Quantity Used Drilling (cu.m)

Waste Management and/or Disposal

- ☐ Solid Waste Disposal
- ☐ Sewage
- ☐ Drill Waste
- ☐ Greywater
- ☐ Hazardous
- ☐ Other:

Additional Details:

A list of unauthorized discharges and a summary of follow-up actions taken.

Spill No.:  (as reported to the Spill Hot-line)

Date of Spill:

Date of Notification to an Inspector:

Additional Details: (impacts to water, mitigation measures, short/long term monitoring, etc)

Not applicable

#### Revisions to the Spill Contingency Plan

N/A - not applicable

Additional Details:

#### Revisions to the Abandonment and Restoration Plan

N/A - not applicable

Additional Details:

#### Progressive Reclamation Work Undertaken

Additional Details (i.e., work completed and future works proposed)

#### Results of the Monitoring Program including:

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where sources of water are utilized;**

Details attached

Additional Details:

Surface water was only utilized for the collection of surface water sampling. No other water was used as part of this project.

**The GPS Co-ordinates (in degrees, minutes and seconds of latitude and longitude) of each location where wastes associated with the licence are deposited;**

Details described below

Additional Details:

Wastes were deposited in the main Landfill area in lifts as described in the annual report. The license application stated that an estimated 3629 m<sup>3</sup> of bulk non-hazardous metal waste was to be deposited. The actual non-hazardous waste total of 1413 m<sup>3</sup> was consolidated and incorporated into the landfill.

**Results of any additional sampling and/or analysis that was requested by an Inspector**

No additional sampling requested by an Inspector or the Board

Additional Details: (date of request, analysis of results, data attached, etc)

**Any other details on water use or waste disposal requested by the Board by November 1 of the year being reported.**

No additional sampling requested by an Inspector or the Board

Additional Details: (Attached or provided below)

**Any responses or follow-up actions on inspection/compliance reports**

No inspection and/or compliance report issued by INAC

Additional Details: (Dates of Report, Follow-up by the Licensee)

**Any additional comments or information for the Board to consider**

No additional comments or information.

**Date Submitted:**

**Submitted/Prepared by:**

**Contact Information:**

	Jackie Barker, Transport Canada
<b>Tel:</b>	204-983-4042
<b>Fax:</b>	204-983-5048
<b>email:</b>	<a href="mailto:jackie.barker@tc.gc.ca">jackie.barker@tc.gc.ca</a>