

EXECUTIVE SUMMARY
2017 Annual Report for TC Licence No. 1BR-MDR1721
Iqaluit Former Vehicle Dump and Community Landfill

The remediation program at the former Iqaluit Metal Dump and Community Landfill was completed in accordance with the provisions outlined in the Remedial Action Plan (RAP) (Arcadis, 2017). The project operated over the period of one summer/fall field season starting on July 25, 2017 and ending on October 13, 2017 with all site activities, including mobilization and demobilization taking place within that timeframe.

The remedial activities were conducted in accordance with the regulatory requirements as stipulated in the Nunavut Water Board (NWB) water license and all applicable regulations dictated by the Government of Nunavut.

Based on the provisions outlined in the Performance and Long-Term Monitoring Plan (LTM), as part of the Nunavut Water Board (NWB) water licence number 1BR-MDR1721 issued July 31, 2017 and associated LTM approval letter dated September 25, 2017, long term monitoring will be undertaken at the site annually until July 30, 2021 to confirm that the environment and human health are being protected.